

Vessel - Demerara (IMO: 9880386)

Inspection Type	006 - Vessel Inspection Report
Inspection Date	08 Sep 2023
Inspector	Vikram Puri
From Port	Chaguaramas
To Port	Chaguaramas
Hours Onboard	12 H
Avg Audit Findings	100 %
No of NCRs	0
No of observation	5
Crew Interview & Atte	ndance Record



Remarks

Rank

Auditor Signature

Vikram Puri





Vessel - Demerara (IMO: 9880386)

Negative F	indings						
Defect ID	Chapter	Category	Question	Answer Details	Is Critical	Status	Link
Additional	NCRs						
Defect ID	NCR No	Observati	ons		Date of Disposition	Sta	atus
Additional	Observations						
Defect ID	Observations	S			Date of Disposition	Sta	atus
0	ALL THE GC T	BE UPDATED				Per	nding
0	GREASING OF ALL THE DECK AND ENGINE ROOM MACHINARIES TO BE CARRIED OUT.			Per	nding		
0	IG LINE MODIFICATION JOB TO BE COMPLETED			Per	nding		
0	TABLES AND	CHAIRS LEG FITTINGS T	O BE PROVIDED.			Per	nding
0	TAGGING OF	ALL THE SPARE MACHIN	ARIES TO BE CARRIED OUT			Per	nding
_							

Positive / Neutral Findings



Vessel - Demerara (IMO: 9880386)

Chapter: 01.00 - Area/Item Inspected

Category: 01.01 - Part I - External Condition

Question	Answer Details	Is Critical	Link
01.01.01 - External Condition - Propeller	Grade - Yes		
	NA		
01.01.02 - External Condition - Rudder	Grade - Yes		
	NA		
01.01.03 - External Condition - Ship's name and Port of Registry	Grade - Yes		
	NA		
01.01.04 - External Condition - Hull - Topside area	Grade - Yes		
	NA		
01.01.05 - External Condition - Hull - Boot top area	NA Grade - Yes		
01.01.06 - External Condition - Draft marks	NA Grade - Yes		
	-		
01.01.07 - External Condition - Plimsoll mark	NA Grade - Yes		
	Glade - Tes		
01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks	NA Grade - Yes		
01.01.06 - External Condition - Bow thruster / Build mark / tank marks	Glade - res		
	NA		
Category: 01.02 - Part II - Decks			
Question	Answer Details	Is Critical	Link
01.02.01 - Decks - Accommodation Ladders - Platform / Wires / Motor	Grade - Yes	is offical	LIIIK
01.02.02 - Decks - Ships name - bridge wings	NA Grade - Yes		
Optomore un 04.02 Dout III - Interne of Usual Otmustures	NA		
Category: 01.03 - Part III - Internal Hull Structure			



Vessel - Demerara (IMO: 9880386)

INKER MANAGEMENT			
Question	Answer Details	Is Critical	Link
Category: 01.04 - Part IV - Mast Houses / Midship Stores			
Question	Answer Details	Is Critical	Link
Category: 01.05 - Part V - Cargo Pump Room			
Question	Answer Details	Is Critical	Link
Category: 01.06 - Part VI - Accommodation Spaces			
Question	Answer Details	Is Critical	Link
Category: 01.07 - Part VII - Navigation Bridge			
Question	Answer Details	Is Critical	Link
Category: 01.08 - Part VIII - Engine Room			
Question	Answer Details	Is Critical	Link
Category: 01.09 - Part IX - Record Keeping			
Question	Answer Details	Is Critical	Link
Category: 01.10 - Part X - Certificates And Approvals			
Question	Answer Details	Is Critical	Link

	Maritec Tanker Management Private Limite	ed		
MARITEC TANKER MANAGEMENT	Vessel - Demerara (IMO: 9880386)			
Category: 01.1	1 - Part XI - Safety Equipment And Alarms			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	2 - Part XII - Environmental			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	3 - Part XIII - Security			
Questio	n	Answer Details	Is Critical	Link
	4 - Comments of the Superintendent Conducting Inspection			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	5 - Random interviews			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	6 - Meeting / Seminars held			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	7 - Near Miss(es) identified			
Questio	n	Answer Details	Is Critical	Link
Category: 01.1	8 - Training needs identified and addressed			

MARTEC TANKER MANAGEMENT	Maritec Tanker Management Private Vessel - Demerara (IMO: 9880386)	e Limited		
Question	1	Answer Details	Is Critical	Link
Category: 01.19	Proposals for the effective implementation/imp	rovement of the SMS		
Question	1	Answer Details	Is Critical	Link
Category: 01.20) - Commercial performance of the vessel			
Question	1	Answer Details	Is Critical	Link
Category: 01.21	- Load sharing capacity of Aux Engine			
Question	1	Answer Details	Is Critical	Link