

Maritec Tanker Management Private Limited

Vessel - Bitu River (IMO: 9918133)

Inspection Type	003 - MLC Internal Audit
Inspection Date	04 Aug 2023
Inspector	Fiacre Fonseca
From Port	Lome
To Port	Lome
Hours Onboard	30 H
Avg Audit Findings	53 %
No of NCRs	0
No of observation	0



Crew Interview & Attendance Record

Staff Name	Rank	Remarks
10019 - Mohsin Abdul Karim Mulla	2/OFF	
10605 - Gurjit Singh .	AB	
10568 - Ashfaaq Mavadigothi	OS	
10608 - Surendra Singh .	C/CK	
10098 - Janardan Yadav	OLR	
10466 - Yacine Blondin Youm	J/OFF	

Auditor Signature

Fiacre Fonseca



Maritec Tanker Management Private Limited

Vessel - Bitu River (IMO: 9918133)

An error has occurred while processing TextBox 'textBox66': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing Table 'table1': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing TextBox 'textBox41': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing Table 'table3': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing TextBox 'textBox13': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing Table 'table2': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing TextBox 'textBox85': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing Table 'list1': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing TextBox 'textBox32': The expression contains object 'Insp_Type' that is not defined in the current context.	
An error has occurred while processing Table 'table5': The expression contains object 'Insp_Type' that is not defined in the current context.	