












M/T BAHAMA
BLUE

MARITEC TANKERS MANAGEMENT Ltd
Record of Electrical Continuity Test for Cargo Hoses

No.	Cargo Hose Serial No.	Date	Result of Continuity Test	Remark	Signature of Electrical Engineer	Signature of Chief Engineer
1	105530850#2	17.10.20	10.6 ohms	Sat.	<u>V. Khan</u>	
2	105530850#4	17.10.20	10.7 ohms.	Sat	<u>V. Khan</u>	
3	105530850#1	17.10.20	11.2 ohms.	Sat.	<u>V. Khan</u>	
4	105530850#3	17.10.20	11.8 ohms.	Sat	<u>V. Khan</u>	
5	105530852#1	17.10.20	12.0 ohms.	Sat.	<u>V. Khan</u>	
6	105530852#2	17.10.20	10.5 ohms	Sat	<u>V. Khan</u>	
7	105530852#3	17.10.20	10.8 ohms	Sat	<u>V. Khan</u>	
8	105594014#4	17.10.20	12.0 ohms	Sat	<u>V. Khan</u>	
9	105594014#3	17.10.20	11.8 ohms.	Sat	<u>V. Khan</u>	
10	105594014#2	17.10.20	10.6 ohms.	Sat.	<u>V. Khan</u>	
11	105594014#1	17.10.20	11.2 ohms.	Sat	<u>V. Khan</u>	
12	105530852#4	17.10.20	—	Damaged.	<u>V. Khan</u>	

M/T BAHAMA
BLUE

MARITEC TANKERS MANAGEMENT Ltd
Record of Electrical Continuity Test for Cargo Hoses

No.	Cargo Hose Serial No.	Date	Result of Continuity Test	Remark	Signature of Electrical Engineer	Signature of Chief Engineer
13	105896287#1		10.7 ohms	Sat		
14	105896285#4		11.5 ohms.	Sat		
15	105896285#3		12.0 ohms.	Sat		
16	105896285#2		12.6 ohms	Sat		
17	105896285#1		12.4 ohms.	Sat		
18	105896287#4		12.6 ohms.	Sat		
19	105896287#3		12.1 ohms	Sat		
20	105896287#2		12.2 ohms.	Sat		
21	105896289#4		12.5 ohms.	Sat		
22	105896289#3		12.4 ohms.	Sat		
23	105896289#2		12.3 ohms	Sat		
24	105896289#1		12.0 ohms.	Sat.	