

ANNUAL INSPECTION OF EEBD

VESSEL : M T BAHAMA BLUE

PAGE 1 OF 2

IMO:9836529

DATE: 23.JAN.2021

This is to certify that following EEBD's were inspected & checked on board and are in good condition.

The following checks were carried out in accordance with the manufacturer's instructions

Tampering – Checked for tampering of the EEBD unit

Read the Pressure Gauge: The tip of the needle on the gauge is normally in the green zone. If the needle is in the red or on the white zero pressure mark, remove the EEBD from service immediately. If the view of the gauge is obstructed, the EEBD must be removed from service.


Visually inspected the apparatus for indications of high force impacts – These includes

- Case cracked, burned, deformed or excessively worn.
- Excessive gap between the Cover and Base.
- Damaged Latch or Cover Band.
- Dirt, debris or moisture visible through the gauge window.
- Broken belt loops.

EEBD :

No	Make/Model	Type of gas cylinder	Serial Number	Capacity(ltr)	Condition
1	HWAYAN	TH15B	1810402	3 L	Good
2	HWAYAN	TH15B	1810403	3 L	Good
3	HWAYAN	TH15B	1810404	3 L	Good
4	FANG-ZHAN	TH/15-1	1811257	3 L	Good
5	FANG-ZHAN	TH/15-1	1811169	3 L	Good
6	FANG-ZHAN	TH/15-1	1811172	3 L	Good
7	FANG-ZHAN	TH/15-1	1811215	3 L	Good
8	FANG-ZHAN	TH/15-1	1811153	3 L	Good
9	FANG-ZHAN	TH/15-1	1811230	3 L	Good
10	FANG-ZHAN	TH/15-1	1811218	3 L	Good

11	FANG-ZHAN	TH/15-1	1811264	3 L	Good
12	FANG-ZHAN	TH/15-1	1811233	3 L	Good
13	FANG-ZHAN	TH/15-1	1811291	3 L	Good
14	FANG-ZHAN	TH/15-1	1811294	3 L	Good
15	FANG-ZHAN	TH/15-1	1811208	3 L	Good
16	FANG-ZHAN	TH/15-1	1811269	3 L	Good
17	FANG-ZHAN	TH/15-1	1811234	3 L	Good
18	FANG-ZHAN	TH/15-1	1811242	3 L	Good
19	FANG-ZHAN	TH/15-1	1811156	3 L	Good
20	FANG-ZHAN	TH/15-1	1811285	3 L	Good
21	FANG-ZHAN	TH/15-1	1811190	3 L	Good


 Chief Engineer




 Master: