



ECR. 11.0 - DAILY WORK DONE REPORT

Date : 10/08/2018

Page No : 1 of 4

Made by : QHSE

Approved by : MD

Rev. No : 0

Vessel: BITU ATLANTIC

Year: 2018

Department: DECK

Date (dd/mm/yy): 30.11.2018

Month: NOVEMBER

Note:

- This form must be filled up on daily basis
- For each department (Deck / Engine / Electrical) a separate work done report is to be prepared.
- The Deck work done report to include Bridge & Accommodation
- Every Sunday the updated electronic copy shall be sent to technical@maritec.be
- At the end of the month, complete signed report shall be sent along with the monthly documents

Date	Place	Work Description
1 st	At Port	Loading of Bitumen Pen 60/70 in progress at Kemmaman. Loadport port watches carried out. Mooring attended, Scuppers organised, Fire wire attended, Gangway & Manifold watch maintained.
2 nd	At Port	Loading of Bitumen Pen 60/70 in progress at Kemmaman. Loadport port watches carried out. Mooring attended, Scuppers organised, Fire wire attended, Gangway & Manifold watch maintained.
3 rd	At Port	Loading of Bitumen Pen 60/70 in progress at Kemmaman. Loadport port watches carried out. Mooring attended, Scuppers organised, Fire wire attended, Gangway & Manifold watch maintained.
4 th	At Sea	Vessel completed loading and departed for Singapore. Mooring stations attended. Gangways secured Secured vessel for sea
5 th	At Port	Vessel arrived Singapore. Prepare combination for Pilot boarding. Attended Anchor stations. Attended Bunker Barge mooring stations. Assisted in connecting / Disconnecting Bunker hose. Attended Departure anchor stations. Bridge watches, Accommodation cleaning. Fire, safety & security rounds taken. Cleaning of steering flat for painting carried out.
6 th	At Sea	Accommodation cleaning. Fire safety & security rounds carried out. Bridge watches. Commenced painting steering flat. Removed cargo reducer from manifold and secured. Renewed IG spectacle flange packing for SLOP P & S COT. Inventory of paint ropom completed. Painting of snap back zone areas on deck in progress. Stencilling of Deck lines in progress.
7 th	At Sea	Accommodation cleaning. Fire safety & security rounds carried out. Bridge watches. Painting of steering flat in progress. Painting of snap back zone areas on deck in progress. Stencilling of Deck lines in progress. Stencilling of Gangways, PV w/v, Mastriser, Deck seal & NRV w/v completed. Greasing of all mooring winches completed. Assisted technician for commissioning of BWMS.
8 th	At Sea	Accommodation cleaning. Fire safety & security rounds carried out. Bridge watches. Painting of steering flat in progress. Vessel experienced heavy rains. Clenting of pumproom bottom for painting completed. Assisted technician for commissioning of BWMS.
9 th	At Sea	Accommodation cleaning. Fire safety & security rounds carried out. Bridge watches. Painting of steering flat in progress. Vessel experienced heavy rains. Testing of Cargo pumps in progress. Painting of pumproom in progress. Assisted technician for commissioning of BWMS. Painting of steering flat completed.

To be filed on board in ECR 11.0 folder



ECR. 11.0 - DAILY WORK DONE REPORT

Date : 10/08/2018

Page No : 2 of 4

Made by : QHSE

Approved by : MD

Rev. No : 0

10 th	At Sea	Accommodation cleaning . Fire safety & security rounds carried out. Bridge watches . Testing of cargo pumps completed. Assisted technician for commissioning of BWMS. Painting of steering flat in progress.
11 th	At Sea	Accommodation cleaning . Fire safety & security rounds carried out. Bridge watches . Assisted technician for commissioning of BWMS. Painting of steering flat in progress.
12 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Overhauling & repair of gangway motor completed. Repairing of No 2 COP suction v/v reach rod completed. Stencilling of pipeline in progress. V/V no stencilling of Hydraulic boxes on main deck completed. Buffing & priming of poop deck & aft spring winch staffa motor completed. Chipping of Emg gen deck completed. Painting & stencilling of Garbage bins for common spaces completed.
13 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Replacement of two leaking foam monitor valves completed. Painting off poop deck area in progress. Topcoat painting of monkey island deck completed. Topcoat painting of Bridge wing deck completed. Chipping & priming of a & b deck completed. Painting of pump room bottom platform in progress. Stencilling of main deck in progress.
14 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Shifting of stores completed. Chipping and priming of funnel deck completed 2 nd court of A & B deck completed. Chipping of air vent pipes, sounding pipes, air vent heads and drip trays in progress. Replacement of WBT gas detection 3-way v/v handles on-deck completed. Painting off poop deck area in progress. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of galley in progress.
15 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Topcoat painting of A , B & C outpassage deck in progress. Chipping of air vent pipes, sounding pipes, air vent heads and drip trays in progress. Painting off poop deck area completed. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of galley in progress. Replacement of 2 fire hydrants & 3 Foam monitor v/v's completed.
16 th	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Topcoat painting of A , B & C outpassage deck in completed. Anchor stations attended for arrival Port Louis. Chipping of air vent pipes, sounding pipes, air vent heads and drip trays in progress. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of galley in progress. Replacement of 2 fire hydrant completed. Lapping of Fire hydrants completed. Chipping & painting of ensign staff completed. Renewal of Port & stbd lifeboat gripes completed.
17 th	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Chipping of air vent pipes, sounding pipes, air vent heads and drip trays in progress. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of galley completed. Painting of officer's pantry in progress. Replacement of 2 fire hydrant completed. Renewal of Port & stbd lifeboat gripes completed. Greasing of fwd & aft firewires completed. Wire lashing of fwd Eta chain completed.
18 th	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Chipping of air vent pipes, sounding pipes, air vent heads and drip trays in progress. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of officer's pantry in progress. Replacement of 3 foam monitor v/v's completed.
19 th	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Chipping & priming of air vent pipes, sounding pipes, air vent heads and drip trays

To be filed on board in ECR 11.0 folder



ECR. 11.0 - DAILY WORK DONE REPORT

Date : 10/08/2018

Page No : 3 of 4

Made by : QHSE

Approved by : MD

Rev. No : 0

		completed. Painting of pump room bottom platform in progress. Stencilling of main deck in progress. Painting of officer's pantry completed. Attended dep anchor stations.
20 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Renewal of conduit lines U clamps in process. 2 coat primer & topcoat of dip tray in process. Chipping and priming of ship railing in process. Pump room painting in progress. Wire lashing and covering of eta chain in process.
21 st	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Chipping and priming of P & Std Manifold area completed. Renewal of conduit lines U clamps in process. 2nd coat primer & topcoat of dip tray, sounding pipes, air vents in process. 2nd coat for ship railing completed Topcoat in process. Pump room painting in progress. ODME TESTED.
22 nd	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. 2ND and topcoat of P & Std Manifold area completed. Renewal of conduit lines U clamps completed. 2nd coat primer & topcoat of dip tray, sounding pipes, air vents completed. Ship railing aft of accommodation Topcoat completed. Pump room painting in progress.
23 rd	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Marking and stencilling of pumproom w/v in progress. Painting of pumproom in progress. Stencilling of drip trays, air vents, sounding pipes aft of accommodation completed. Lashing of all loose materials on deck and in stores completed. Buffing and priming of Bisulphite and hypochlorite pipes of BWMS on main deck completed.
24 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Marking and stencilling of pumproom w/v in progress. Painting of pumproom in progress. Arranging and inventory of deck store in progress. Painting & stencilling of garbage bins for crew cabins in progress. Painting of steering flat in progress.
25 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Marking and stencilling of pumproom w/v completed. Painting of pumproom in progress. Arranging and inventory of deck store in progress. Painting & stencilling of garbage bins for crew cabins completed. Painting of steering flat in progress. Arranging of dry provision store completed.
26 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Painting of pumproom in progress. Arranging and inventory of deck store completed. Painting of steering flat in progress. Greasing of ventilators sounding pipes in progress. Forepeak store painting in progress.
27 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Painting of pumproom in progress. Painting of steering flat in progress. Greasing of ventilators sounding pipes in progress. Forepeak store painting in progress. Stencilling of main deck in progress.
28 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Painting of pumproom in progress. Painting of steering flat in progress. Greasing of ventilators sounding pipes in progress. Forepeak store painting completed. Stencilling of main deck in progress. Chipping and priming of aft fire wire reel completed. Marking of muster station & lifeboat stations in progress.
29 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Painting of pumproom in progress. Stencilling of pumproom in progress. Painting of steering flat in progress. Greasing of ventilators sounding pipes completed. Stencilling of main deck in progress. Marking of muster station & lifeboat stations completed. Painting of green way with anti slip on main deck completed.
30 th	Choose a place	Accommodation cleaning. Fire safety & security rounds taken. Bridge watches. Painting of pumproom completed. Stencilling of pumproom in progress. Painting of steering flat completed. Greasing of Gangways completed. Greasing of hydraulic boxes, tankdome, Wbt manhole butterfly nuts completed. Stencilling of main deck in progress.

To be filed on board in ECR 11.0 folder



ECR. 11.0 - DAILY WORK DONE REPORT

Date : 10/08/2018

Page No : 4 of 4

Made by : QHSE

Approved by : MD

Rev. No : 0

Name Chief Engineer (for Engineer
report)

Signature

Gueros Sincay

Name Chief Officer (for Deck report)

[Signature]

Signature