



ECR. 11.0 - DAILY WORK DONE REPORT

Date	: 10/08/2018
Page No	: 1 of 3
Made by	: QHSE
Approved by	: MD
Rev. No	: 0

Vessel: BITU ATLANTIC

Year: 2018

Department: DECK

Date (dd/mm/yy): 31.01.19

Month: January

Note:

- This form must be filled up on daily basis
- For each department (Deck / Engine / Electrical) a separate work done report is to be prepared.
- The Deck work done report to include Bridge & Accommodation
- Every Sunday the updated electronic copy shall be sent to technical@maritec.be
- At the end of the month, complete signed report shall be sent along with the monthly documents

Date	Place	Work Description
1 st	At Port	LOME PORT – discharging operations. Arrange provision rcvd on this port. Manouevring from Lome Port
2 nd	At Port	STS Operation with MT Biskra Double watch for mooring lines due to heavy rolling; repair and replaced continuous the mooring lines in order to keep MT Biskra alongside
3 rd	At Port	STS Operations with MT Biskra Double Watch for mooring lines fore and aft , adjus and repair continous Manouevring Operations – Cast Off MT Biskra Departure from Off Shore Lome – arrange the vessel for sea condition
4 th	At Sea	Full Washing Accomodation – remove carbons from all decks Disconnect cargo hose from manifold, lifted in position. Replace goose neck thermal valve on fwd part of the termal lines. Arrange drinking water inside accomodation. Secure 3 tyre fenders on board.
5 th	At Sea	Accomodation cleaning. Fire safety & security rounds taken . Bridge watches. Start Gas Free Operation COT 7 P / 7 S / 3 P / 3 S Cleaning inside Pump Room – COP Cleaning and Pump Room Bilges Cleaning inside Accommodation, Crew Laundry Room Chipping & Brushing and priming main deck aft area. Fire & LB & Pollution drill carried out.
6 th	At Sea	Accomodation cleaning. Fire safety & security rounds taken . Bridge watches. Gas Free Operation in progress for inspection COT 7 P / 7 S / 3 P / 3 S Cleaning inside Pump Room – COP Cleaning and Pump Room Bilges. Painting Main-deck – aft area. Arrange Mooring ropes on aft / Clean inside Midship Locker.
7 th	At Sea	Accomodation cleaning. Fire safety & security rounds taken . Bridge watches. Inspection COT 1 P / 1 S 3 P / 3 S Cleaning inside Pump Room – COP Cleaning and Pump Room Bilges. Repair Steam Valve in pump room with leaking / remove water Splicing of mooring ropes on forward and aft.
8 th	At Sea	Accomodation cleaning. Fire safety & security rounds taken . Bridge watches. Brushing / washing / priming Thermal bottle room aft off Officers Deck / funnel Arrange store / intems / inventroy on Safety Locker

To be filed on board in ECR 11.0 folder




ECR. 11.0 - DAILY WORK DONE REPORT

Date : 10/08/2018
 Page No : 2 of 3
 Made by : QHSE
 Approved by : MD
 Rev. No : 0

		Remove / Compact Garbage from Garbage Area Grease forward winches and Springs
9 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Cleaning and painting main floor on New Scrubber Room Grease aft winches and Springs aft / grease port & stbd Gangways
10 th	At Sea	Cleaning & arrange garbage area – repaint the drums for garbage on aft. Splicing mooring ropes on aft side Painting scrubber room floor; cleaning inside accommodation – crew mess room Open WBT Manhole for exchange the ballast. Ballast exchange in progress. Greasing Thermal Oil Valves in main deck.
11 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Exchange Ballast Opretations in progress. Brushing chipping and cleaning New Scrubber room top platforms. Fire / Life Boat drills / Training carried out with all crew members.
12 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Priming New Scrubber room top platform Cleaning and arrange Paint Store Room. Chipping brushing and priming mooring bits. Stanciling SOPEP Containers and Cargo Hose. Greasing accommodation doors around acomodations.
13 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Arrange and Compact Garbage. Paint main deck aft doors, Clean and remove grease on th aft side. Painting Pump room entrance.
14 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Arrange and secure all items in main deck during heavy rolling
15 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Heavy rolling
16 th	At Sea	Prepare vessel fo arrival at Agios Theodoroi / Wash Main deck / Pre Arrival Test carried out for loading
17 th	At Port	Manouvering, Loading operations in Agios Theodoroi Port
18 th	At Port	PSC Inspection / Loading Operation

19 th	At Port	Loading Operations in Agios Theodoroi Port
20 th	At Port	Loading Operations in Agios Theodoroi Port / Departure station and anchore stations.
21 st	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Garbage landing. Receving stores and arranging them.Repair work on BWMS.
22 nd	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Repair work nof ballast pump completed. Buffing of PV v/v and void space vents completed. Priming of PV v/v and void space vents in process. BWMS work in progress.
23 rd	At Anchorage	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Priming of PV v/v and void space vents in progress. BWMS work in progress. Preparing box for FW hose completed.
24 th	At Port	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Pre loading checks done.
25 th	At Port	Loading Operations in Agios Theodoroi Port
26 th	At Sea	Loading Operations in Agios Theodoroi Port completed. Manouvering from Agios theodoroi. Recived lub oil, bunker and ropes at Pirleus anchorage.
27 th	At Sea	Accomodatlon cleaning. Fire safety & security rounds taken . Bridge watches. Priming of PV v/v and void space vents in progress. Securing on deck.
28 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Priming of PV v/v and void space vents in progress.Painting in galley. Prepared fw

To be filed on board in ECR 11.0 folder


	ECR. 11.0 - DAILY WORK DONE REPORT	Date : 10/08/2018
		Page No : 3 of 3
		Made by : QHSE
		Approved by : MD
		Rev. No : 0

		hose. Deck danger zone marking in progress.
29 th	At Sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Priming of PV v/v and void space vents in progress. Denso tape on hydraulic pipelines. Deck danger zone marking in progress. Pump room floor cleaning.
30 th	At Sea	Accommodation / galley/ bridge cleaning. Fire safety & security rounds taken . Bridge watches. Changing rope on winches completed. Commence cargo heating. Painting on deck. Prepared tyre for STS.
31 th	At sea	Accommodation cleaning. Fire safety & security rounds taken . Bridge watches. Hot work on C deck. Preparing fenders for STS. Cargo pump heating started.

Name Chief Engineer (for Engineer report)

Signature

ANIVESH CHOBEY
Name Chief Officer (for Deck report)



Signature

