

#### **B. 5.20 - DRILL REPORT**

Date : 10/08/2018 Page : 1 of 2

Made by : QHSE Approved by : MD Rev. No : 0

Vessel :MT BITU ATLANTIC Date (dd/mm/yy):27.10.2018 Location:AT SEA

Type of Drill : BOMB SEARCH DRILL

Description of Planned Drill: -

ACTION TO BE TAKEN IN CASE BOMB SEARCH DRILL,

### **SOLAS** Requirements for Conducting Abandon Ship Drill and Fire Drill:

### SOLAS Ch III Reg 19 3.3 Requires Abandon Ship Drill Should Include atleast following: -

- Raising of Alarm and Mustering of Crew at Muster stations,
- Preparing for Their Duties as described in Muster List,
- Checking that Crew is appropriately dressed and Life jackets properly donned,
- Lowering of at least one Life boat after necessary preparation, (Not for free fall Life Boats),
- Starting and operating Life boat Engine,
- Operating Davits used for Launching Life rafts,
- Mock search and Rescue of Crew Trapped in Staterooms,
- Instructions in use of Radio Life Saving Appliances.

## SOLAS Ch III Reg 19 3.4 Requires Fire Drill Should Include at least following: -

- Fire Drills should be planned so as to have regular practice in various emergencies that may occur depending upon type of vessel,
- Reporting for stations and Preparing for Their Duties as described in Muster List,
- Starting Fire pump using at least 2 jets of water,
- Checking of fireman's outfit and other personal rescue equipments,
- Checking operation of water tight doors, fire doors, fire dampers and ventilation systems in area of drill,
- Check necessary arrangements for subsequent abandoning of the ship.


# Log Of Events Of Drill: - Each and every reported event to Bridge has to be recorded with time as below: -

### After initial Alarm Sounded crew muster at Emergency Muster Station: -

Time	Event	Reported By
1700	Alarm Sounded, Nature of drill declared by Master: BOMB SEARCH DRILL.	MASTER
1701	Crew Mustered	3RD OFF
1702	Head Count Taken- Missing Persons	3RD OFF
1704	Checking of PPE Done	3RD OFF
1705	Duties Checked / Explained	3RD OFF

### Master declares the nature of emergency and Emergency team Organisation done as below: -

Time	Event	Reported By
1708	MASTER explained the procedures in case of the bomb search	MASTER
	Keeping of records of all events, procedure for searching bomb by diffrent parties, and precautiion to be taken by	MASTER
	Not to touch any supicious object located ,sealing of the area ,risk of fire , rigging of fire equipments	MASTER
	Office notification, shore authorities/cost should be advise,if port evacuate non essential person and wait for the shore search team	MASTER



**Evaluation Of Drill for improving the training and response of crew in emergency: - This Should be based upon follwoing: -**

- Response of Crew in Drill as observed by all Team Leaders and Master,
- Feedback from Crew Members for effective improvemnet of Response,
- Identification for Further training requirements should be aimed for improvement.

ALL SATISFACTORY.			

### **Drill Attendance Log:-**

Sr. No	Name	Rank	
1	CAPT. PANAIT MARIN	MASTER	
2	SILVESTRE A FERNANDES	3RD OFF	
3	ANDRIESANU DUMITRU	CH.ENG	
4	ANGELADA ARSENIO JR. CERVANTES	2ND ENG	
5	PASCUAL HERWIN CELORICO	3RD ENG	
6	MARTINEZ LEOLOR ADAM BEQUILLA	4TH ENG	
7	KARTHIKEYAN KRISHNAN MOOKIA	ELEC.OFF	
8	ADI VENANCIO MONDEJAR	BOSUN	
9	BAILO LYNDON BANDOLA	PUMPMAN	
10	LUMAWAG JEFFREY RIEGO	AB-1	
11	OLAC WILMAR TIPSAY	AB-2	
12	DE MESA JOE VENSON	AB-3	
13	AMPOLOQUIO LEO RABI	OS-1	
14	PAJO JIMBOY VILLANUEVA	OS-2	
15	SHUKLA SUNIL KUMAR	FTR-1	
16	SILIGAN GREGORIO JR	FTR-2	
17	LABRADOR RYAN AROLLADO	OILER-1	
18	SEBUCO MARK ANTHONY EMBOLODE	OILER-2	
19	SIBAYAN DENNIS	CH.COOK	
20	BAUTO JERWIN CHUAHAP	MESSMAN	
21	SHARMA GAGANDEEP	ELEC.SUPT	

Safety Officer : - Name: Gurdas Shing

Master : - Name: <u>Capt. Panait marine</u>