



STATEMENT(LIFEBOAT ARRANGEMENTS)

This is to confirm that the following lifeboat arrangements have been carried out periodic maintenance by the undersigned licensed service engineer in accordance with SOLAS Regulation III 20.3.2 and MSC.402 (96) and that these lifeboat arrangements have been found to be fit for purpose.

Statement No: 022232

Name of Ship:	BITU EXPRESS	IMO No.	9265689
Lifeboat	Type:	S: 21474 / P: 18337 / S2-53-TIR	
	Serial number:	21474 / 18337	
	Date of manufacture:	S: 05.2017 / P: 02.2003	
	Manufacturer:	SHIGI SHIPBUILDING CO.,LTD.	
Release Gear	Type:	S: S2K-7 / P: S2S37M	
	Manufacturer:	SHIGI SHIPBUILDING CO.,LTD.	
Name of owner or Ship manager	PICKETT SHIPPING CORP		
Shipyards	MARITEC TANKER MANAGEMENT		
Hull No.	SHIN KURUSHIMA DOCKYARDS		
Type of ship	5183		
Class	ASPHALT TANKER		
Flag	RINA		
	PANAMA		

Date of Servicing	20.08.2021
Port of Servicing	Yalova - Türkiye
Kind of Servicing	<input type="checkbox"/> Repair <input checked="" type="checkbox"/> Annual thorough examination <input type="checkbox"/> 5year thorough examination

Remarks:

Last Date of Servicing	Last Service Company	Last Certificate No.	Last Statement No.
17.09.2020	BENEMAR	H-52-680B	020162

Service Company	ONURSAN	Captain signature
Certificate No.	H-52-608C	
Service Engineer signature		Owner or Ship manager signature

Note:

1.This statement is based on an arrangement in the deliberation of the 48th IMO Ship Design and Equipment(DE) subcommittee

2.See copies of the certificate on the reverse side

SHIGI SHIPBUILDING CO.,LTD. [For Ship]

ANNUAL THOROUGH EXAMINATION REPORT (1/4)

This report should be issued by the manufacturer's representative or by the person certified by the manufacturer for the work.

1) Hull part No.1 Boat No.2 Boat Date: 20.08.2021

No	Items	Result of inspection and servicing			Remarks	
1	Outside hull	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Repair is necessary			
2	Outside canopy	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Repair is necessary			
3	Buoyant lifeline	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
4	Enclosure structure	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	Partially enclosed lifeboat	
5	Inside structure	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
6	Release gear	Check the status of reset.	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Adjustment is necessary	Overhaul and checking actuation under 1.1 times of load should be done every five years.	
		Check that there is no dirt or foreign matter on the moving part.	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Cleaning is necessary		<input type="checkbox"/> Adjustment is necessary
		Check installing status of fixing part of the hook to the hull.	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary
		Check that simultaneous releasing can be implemented normally.	<input checked="" type="checkbox"/> Good			<input type="checkbox"/> Adjustment is necessary
		Check that reset of hook can be implemented easily.	<input checked="" type="checkbox"/> Good			<input type="checkbox"/> Adjustment is necessary
		Check the actuation of water pressure interlock.	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Repair is necessary
		Check that hook control cable is actuated normally	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Repair is necessary
7	Painter release Device	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Adjustment is necessary		
8	Doors and hatches	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Cleaning is necessary		
9	Window	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
10	Steering gear and rudder	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
11	Stern tube	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
12	Propeller and Propeller guard	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary		
13	Breather valve	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Adjustment is necessary		
14	Drain valve and plug	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Adjustment is necessary		
15	Air Supply Device	Pipe line	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	Fire protected lifeboat	
		Air regulator	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary
		Air reservoir	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary
16	Water Spray Device	Pump	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	Fire protected lifeboat	
		Clutch & Vee belt	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary
		Spray main	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary
		Nozzle	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary		<input type="checkbox"/> Adjustment is necessary

Notice :

Service Company	ONURSAN	Service Engineer signature :	Captain signature :
Certificate No.	H-SZ-603C	<i>Kamer KILIC</i> Service Engineer	



ANNUAL THOROUGH EXAMINATION REPORT (2/4)

This report should be issued by the manufacturer's representative or by the person certified by the manufacturer for the work.

2) Engine part No.1Boat No.2 Boat Date: 20.08.2021

No	Items	Result of inspection and servicing			Remarks
1	General	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
2	Engine	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
	Steering equipment	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Adjustment is necessary	
3	Fuel oil tank	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
Notice :					

3) Electrical part No.1Boat No.2 Boat Date: 20.08.2021

No	Items	Result of inspection and servicing			Remarks
1	Storage battery	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
2	Interior light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
3	Canopy light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
4	Searching light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
5	Compass light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
6	Electrical wiring	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Repair is necessary	
Notice :					

ONURSAN
Lifeboat Davit & Winch Service

Service Company	ONURSAN	Service Engineer signature :	Captain signature :
Certificate No.	H-SZ-603C	Kamer KILIC Service Engineer	

SHIGI SHIPBUILDING CO.,LTD.



ANNUAL THOROUGH EXAMINATION REPORT (3/4)

This report should be issued by the manufacturer's representative or by the person certified by the manufacturer for the work.

4) Equipment part No.1 Boat No.2 Boat Date: 20.08.2021

No	Items	Result of inspection and servicing			Remarks
1	Oar	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
2	Clutch	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
3	Boat Hook	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
4	Bailer	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
5	Bucket	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
6	Survival Manual	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
7	Compass	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
8	Sea anchor	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
9	Painter	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
10	Hatchet	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
11	Freshwater tank	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
12	Dipper	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
13	Drinking vessel	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
14	Food ration	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	Effective period: 5years
15	Distress signal set	Parachute signal	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	Effective period: 3.5years
		Hand flare	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
		Buoyant smoke signal	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
16	Water proof electrical torch	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
17	Daylight signalling mirror	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
18	Life-saving signalling table	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
19	Whistle	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
20	First-aid outfit	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	Effective period: Pack-A 2.5years Pack-B
21	Anti-seasickness medicine and Seasickness bag	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
22	Jackknife	<input checked="" type="checkbox"/> Good		<input type="checkbox"/> Part exchange is necessary	
23	Tin opener	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
24	Buoyant rescue quoit	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	<input type="checkbox"/> Replenishment is necessary	
Notice :					

Service Company	ONURSAN	Service Engineer signature	Captain signature :
Certificate No.	H-SZ-603C	<i>Kamer KILIC</i> Service Engineer	



ANNUAL THOROUGH EXAMINATION REPORT (4/4)

This report should be issued by the manufacturer's representative or by the person certified by the manufacturer for the work.

4) Equipment part No.1 Boat No.2 Boat Date: 20.08.2021

No	Items	Result of inspection and servicing		Remarks
25	Manual pump	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
26	Fishing tackle	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
27	Tool for engine	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
28	Portable fire extinguisher (Froth or Powder)	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	Effective period: Froth 1 year
29	Search light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
30	Rader reflector	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
31	Thermal protective aids	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary <input type="checkbox"/> Replenishment is necessary	
32	Locker	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
33	Rain water tank	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
34	Canopy light	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
35	Boarding ladder	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
36	Seat belt	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary <input type="checkbox"/> Replenishment is necessary	
37	Emergency operating manual	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
38	Dye marker	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Part exchange is necessary	
Notice :				

ONURSAN
Lifeboat Davit & Winch Service

Service Company	ONURSAN	Service Engineer signature :	Captain signature :
Certificate No.	H-SE-603C	Kamer KILIC Service Engineer	

SHIGI SHIPBUILDING CO.,LTD.

Certificate of Lifeboat Service Engineer



Certificate No. **H-SZ-603C**
Term of Validity: **Sep 30 2022**
Name : **Kamer Kilic**
Date of Birth : **Jul 10 1979**
Name of Belonged Company :
Onursan Co., Ltd.

Date of Issue : **Oct 01 2019**
SHIGI SHIPBUILDING CO., LTD.

(signature) *R. Tanino*
Quality Assurance Group : Ryo Tanino

Kamer Kilic

is certified to carry out servicing and maintenance of
SZ series, FEL series, VOX series, GARS series, OPEN type,
and release gear manufactured by
Shigi Shipbuilding Co., Ltd.

Qualification levels provided by the manufacturer,

Annual thorough examinations and operational tests (Par. 4.2)

Five-year thorough examination, any overhaul, overload operational tests (Par. 4.3)

This certificate of service engineer is created based on MSC.402(96) and is issued

Shigi Shipbuilding Co., Ltd.

3-36 Dejimanishi-machi, Sakaiku, Sakai-city, Osaka, Japan 590-0831
Tel: +81 72 241 2033 Fax: +81 72 244 1728