

**Before** 

## Maritec Tanker Management Daily Meeting Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bahama Blue Defect ID: 112 NCR#: Is NCR?: No **Defect Details** one light cover cracked - stbd catwalk aft Requisition Code: Categories Vessel Dept: Electrical Primary: Accomodation Inspector - Internal: Athma Gopaul Inspector External: Office Dept: Safety Electrical Secondary: Appliances Inspection Date : 04-Apr-2022 **Applicable Dates** Date Raised: 04-Apr-2022 ETC: 31-May-2022 Date Completed: 11-Jun-2022 Other Details Priority: Normal Assigned By: Vessel Verified By: Display in Daily Meeting? : Yes SFI: Verified On: Causes **Corrective Action Preventive Action Applicable Tags** Follow Up On Ву **Follow Up** 12/Apr/2022 Athma Gopaul **Before & After Pictures** 

Daily Meeting Details Printed On: 20-Jun-2023 1/2

After



