

Maritec Tanker Management Private Limited

Incident Reports Details

Vessel : Asp	halt Teranga	Defect ID	9 : 190	NCR # :	32/2023		ls N	CR ? : Yes		
Defect Details										
During PSC inspection on 29.09.2023										
Inappropriate procedures for the processing of garbage are stated in the GMP.)the vessel is not fitted with the incinerator according to the IAPP Certificate and the type approval certificate for the comminuter is missing)										
Requisition Code :										
Categories										
	Incident	Increa						Dask		
Primary :	Incident		ctor - Internal :	Vessel Dept : Deck						
Secondary :	Other	Inspe	ctor External :			Office Dep	ot :	Management		
		Inspe	ction Date :							
Applicable Da	Applicable Dates									
Date Raised : 29-Aug-2023			ETC: 30-Sep-2023			Date Completed : 30-Sep-2023				
Other Details										
Priority : Normal			Assigned By : Vessel			Verified By : Nawin Khaware				
Display in Daily Meeting? : No			SFI :			Verified On : 13/Oct/2023				
Causes										
Missing information on certificate										
Corrective Action										
GMP corrected / updated. IAPP was renewed by RINA Class 30.09.2023										
Preventive Action										
Ship Certificates & manuals must be checked and verified regularly to ensure up-to-date copies are maintained on board.										
CONTRIBUTING FACTORS										
Root Causes- Job Factor										
Inadequate Leadership and / or Supervision										
Root Causes- Management Factors										
Document / Drawing Control Issue										
Inadequate Monitoring / Supervision										
Follow Up										

On	Ву	Follow Up								
13/Oct/2023	Nawin Khaware	With submitted ev closed now.	vidence, this NC could be considered as							
Before & After Pictures										
Before			After							
	Notification									
L	ETTER OF CONFIRMATION		File Not Uploaded							
This is to confirm that afte	r Maritec Tanker Mgmt. Ltd took owners	hip of MT								

As per ship Garbage Management Plan, incinerator is not mentioned and all garbage, oil residue, operational wastes etc. are landed to MARPOL shore reception facilities.

ASPHALT TERANGA, Incinerator was found non-operational and not in use.

In IAPP certificate, incinerator is not included and we have additionally placed a poster "NOT IN USE" on the equipment.

Master

ASPHALT TERANGA





Type: _{NA} COMPACTOR: Make:NA

Type: NA

COMMINUTER:

Make: COPMAK Type: DISPOSER Location: GALLEY Categories of garbage that will be processed: FOOD WASTE (B) Responsible officer: Chief officer Crew nominated for operation: Chief cook Notification



File Not Uploaded