



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Morbihan	Defect ID : 75	NCR # : 1/2023	Is NCR ? : Yes
-------------------	----------------	----------------	----------------

Defect Details

Vessel facing problem during taking cargo tank ullage as both UTI landed shore for servicing and vessel does not have any standby UTI.
Vessel have 2 MMC which is open type (During Ullaging time-vapour comes out) and only have interface reading.

Requisition Code :

Categories

Primary :	Cargo Handling	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept :	Operations
		Inspection Date :	17-Jan-2023		

Applicable Dates

Date Raised : 18-Jan-2023	ETC : 25-Jan-2023	Date Completed : 13-Apr-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

job factors

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Excessive Wear and Tear

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Follow Up

On	By	Follow Up	
----	----	-----------	--

20/May/2023	Oleg Kisiliuk Staff Code - 10558 - C/OFF	On board two UTI with calibration certificate and in good condition	Link1 Link2
03/Mar/2023	Giorgica Mardaru Staff Code - 10548 - MST	On February 24, I received an UTI at DDC	Link1
18/Jan/2023	Cosmin Otelea Staff Code - 10502 - C/OFF	Waiting for UTI on board after servicing.	

Before & After Pictures

Before	After
---------------	--------------