

Maritec Tanker Management Private Limited

Ship File No	:1	N/A
Office File No	:1	N/A
Form No	:1	N/A
Issue	:1	N/A
Revision	:1	N/A
Rev Date	:1	N/A

Non Conformance Details

Vessel : Aspl	halt Teranga	Defect ID	: 235	NCR # : 9/2024	ls	Is NCR ? : Yes		
Defect Details								
Corrective action taken on the ISM system by the Company is required within 3 months. Deficiency(s) marked ISM is (are) objective evidence of a failure, or lack of effectiveness of the implementation of the ISM code. The ship will be elligible for reinspection after 3 months from the final date of report.								
Requisition Code :								
Categories								
Primary :	SMS	Inspec	Inspector - Internal :		Vessel Dept	Deck		
Secondary :	Quality & Safety Procedures	Inspec	Inspector External :		Office Dept :	QHSE		
		Inspec	ction Date : 2	29-May-2024				
Applicable Dates								
Date Raised :	Date Raised : 29-May-2024 ETC : 29-Aug-2024)24	Date Completed : 15-Aug-2024				
Other Details								
Priority : Normal		Assigned By : Port State Control		Verified By: Nawin Khaware				
Display in Daily Meeting? : No		SFI :		Verified On : 11/Sep/2024				
Causes								
Gaps identified in implementation of SMS onboard.								
Corrective Action								
Vessel will be undergoing Internal audit before 29th Aug 2024.								
Preventive Act	tion							
Master to ensure compliance with company SMS guidelines. A regular checks on proper implementation of SMS requirements to be carried out by Ship's Master.								
Root Causes- Job Factor								
Inadequate Leadership and / or Supervision								
Root Causes- Management Factors								
Document / Drawing Control Issue								
Inadequate Monitoring / Supervision								
Direct Causes- Unsafe Acts								

Other Substandard Act(s)

Job Factors

Inadequate Supervision

Follow Up					
On	Ву	Follow Up			
11/Sep/2024	Nawin Khaware	Internal audit has been completed on 15th Aug 2024.			
28/Jun/2024	Nawin Khaware	Internal Audit is p			
06/Jun/2024	Nawin Khaware	Internal audit report to be uploaded once same is carried out onboard.			
Before & After Pictures					
Before		After			