



# Maritec Tanker Management Private Limited

## Non Conformance Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 234	NCR # : 8/2024	Is NCR ? : Yes
--------------------------	-----------------	----------------	----------------

### Defect Details

Found information booklets intact and damage stability for loading instrument and test cases in copy and not approved at satisfaction of Panama administration after Flag change, (approved by BV under Marshall Islands flag) at the same time the examination and test report certificate for onboard loading instrument found only in copy.

Requisition Code :

### Categories

Primary :	Cargo Handling	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept :	Technical
		Inspection Date :	29-May-2024		

### Applicable Dates

Date Raised : 29-May-2024	ETC : 12-Jun-2024	Date Completed : 06-Jun-2024
---------------------------	-------------------	------------------------------

### Other Details

Priority : Normal	Assigned By : Port State Control	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 06/Jun/2024

### Causes

Failure to follow procedure

### Corrective Action

Immediately informed office ,RINA class has been informed and intact and damage stability booklet for loading instrument and test cases has been endorsed/approved by RINA class on behalf of Panama administration on 30.05.2024.

### Preventive Action

All vessel Manuals to be checked and verified properly before and during all Class attendance.  
All original manuals to be kept in Master cabin.

### CONTRIBUTING FACTORS

#### Root Causes- Job Factor

Inadequate Leadership and / or Supervision

#### Root Causes- Management Factors

Inadequate Monitoring / Supervision

#### Root Causes- Personal Factor

Incorrect Information

Direct Causes- Unsafe Acts

Failure to Follow Rules and Regulations

Substandard Acts

Failure to follow procedure

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------

TO BE PLACED ON BOARD

Herbert-ABS Software Solutions LLC  
CargoMax 2.1 for Windows

Stored Characteristic Booklet

Comprehensive Specific and Detailed Data Used  
Within the CargoMax Loading Program

Bureau Veritas Marine & Offshore  
Sector 028451  
VU  
Process: 07 Aug 2020  
Electronic document  
The plan approval office

Prepared for  
MARITEC TANKER MANAGEMENT PVT LTD  
For the  
Asphalt Teranga  
IMO No: 9263942, Hull No: 531  
Builder: Brodogradiliste Krajevica Dd - Croatia

Prepared by:  
Herbert-ABS Software Solutions LLC  
1040 Mariner Village Parkway, Suite 200 Alameda, CA 94501

Document No. 2020-01171-03  
Revision 0  
June 2, 2020

APPROVED BY SIGN ON  
BEHALF OF THE GOVERNMENT  
OF PANAMA

RINA  
APPROVED  
AUGUST 24/2024

Notification



File Not Uploaded

APPROVED BY RINA ON BEHALF OF THE CONTRACTOR OF PANAMA



TO BE PLACED ON BOARD

Herbert-ABS Software Solutions LLC  
CargoMax 2.1 for Windows

# Direct Calculation of Damage Stability Booklet

Implementation System and Supporting Calculations  
Within the CargoMax Loading Program

Prepared for  
**MARITEC TANKER MANAGEMENT PVT LTD**  
For the  
**Asphalt Teranga**  
IMO No: 9263942, Hull No: 531  
Builder: Brodogradistie Kraljevica Dd - Croatia

Prepared by:  
**Herbert-ABS Software Solutions LLC**  
1040 Mariner Village Parkway, Suite 200 Alameda, CA 94501

Bureau Veritas Marine & Offshore  
Section: 02845U  
**REVIEWED**  
only for plans concerning Classification and as per contract  
Pireaus, 07-Aug-2020  
(Electronic document)  
The plan approval office

Document No.: 2015-00534-02  
Revision: 0  
June 2, 2020

Bureau Veritas Marine & Offshore  
Section: 02845U  
Document checked for STABILITY purposes under the conditions stated on the ATTACHED DOCUMENT #: HPO20046  
Pireaus, 07-Aug-2020  
(Electronic document)  
The plan approval office

FOR LONGITUDINAL STRENGTH

## Notification



File Not Uploaded

APPROVED BY RINA ON BEHALF OF THE CONTRACTOR OF PANAMA



TO BE PLACED ON BOARD

Herbert-ABS Software Solutions LLC  
CargoMax 2.1 for Windows

# Vessel Information Booklet

General Vessel Information, Program Options, and Class Approval Information  
for the CargoMax Loading Program

Prepared for  
**MARITEC TANKER MANAGEMENT PVT LTD**  
For the  
**Asphalt Teranga**  
IMO No: 9263942, Hull No: 531  
Builder: Brodogradistie Kraljevica Dd - Croatia

Prepared by:  
**Herbert-ABS Software Solutions LLC**  
1040 Mariner Village Parkway, Suite 200 Alameda, CA 94501

Bureau Veritas Marine & Offshore  
Section: 02845U  
**REVIEWED**  
only for plans concerning Classification and as per contract  
Pireaus, 07-Aug-2020  
(Electronic document)  
The plan approval office

Document No.: 2015-00534-01  
Revision: 0  
June 2, 2020

Bureau Veritas Marine & Offshore  
Section: 02845U  
Document checked for STABILITY purposes under the conditions stated on the ATTACHED DOCUMENT #: HPO20046  
Pireaus, 07-Aug-2020  
(Electronic document)  
The plan approval office

FOR LONGITUDINAL STRENGTH

## Notification



File Not Uploaded

Report certificate for on board loading instrument found only in copy.

Other comments:  
Date: 30/09/2024



**Notification**

File Not Uploaded

Name of ship	ASPHALT TERANGA	RINA number	100100	IMO number	926242	Job number	118
Port of survey	AUGUSTA	Date of survey	30/09/2024	File	24	AU	415
							01
Item N. PSC/FSI report	PSC code	Action PSC (openly code)	Inspected (Yes/No)	Deficiency description (nature of defect)	Detail actions taken, to rectify the deficiency (if rectified before departure), or temporary measures adopted to ensure seaworthiness/conditional certificates or other		
3	01101	16	YES	In form E of Sulfur Certificate S-VDR find In form R of Sulfur Certificate find MF solution instead of MCR-F solution (GROSS Station fitted with HIF Radio-telegraphy and cable porting)	Form E of Sulfur Certificate has been updated accordingly with VDR MF/FWF fitted		
4	0104	16	YES	In form E of Sulfur Certificate S-VDR find In form R of Sulfur Certificate find MF solution instead of MCR-F solution (GROSS Station fitted with HIF Radio-telegraphy and cable porting)	Form E of Sulfur Certificate has been updated accordingly with VDR MF/FWF fitted		
5	02108	17	YES	During the inspection, the crew has been notified as per Owner's request and according to the IS 11-A11.1, inspection has been carried out on 30/09/2024. All has been completed on 30/09/2024. With reference to the deficiencies noted in PSC/FSI report on per attached form 6, the following has been carried out: * Code 301 to be used for items found to be deficient	As per 11-A11.1.1, 1 is not out of service on 30/09/2024 due to maintenance. This ship is provided with N.3 generators with an electric power of 1104kW each. According to the load balance (Dwg. 070-006-028980-229 dated 06/04/2004), the ship is still in compliance with SOLAS 22 with one auxiliary generator out of service. Issued Class Condition R-11.1.A		
6	02103	16	YES	Found information booklet intact and damage in copy, and an approved and dated test case approved by BV. No change of the status from the command or ship test.	Original information booklet intact and damage stability for loading in copy, and an approved and dated test case approved by BV. No change of the status from the command or ship test.		

**PSC/FSI FOLLOW-UP REPORT**



**Notification**

File Not Uploaded