

## **Near Miss Details**

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.										
Vessel : Demerara				Defect ID : 76						
Defect Details										
On his daily routine on deck, Chief Officer in order to verify that all life buoys were properly placed in position noticed that on a life buoy from poop deck , the life line was not properly attached. The life line was fastened on the grabbing rope of the life buoy instead of the life buoy itself.										
Requisition Code :										
Categories										
Primary :	Near Miss		Vessel Dept :		Deck					
Secondary :	Lack of Skill	Lack of Knowledge / Skill		Dept :	Safety					
Applicable Dates										
Date Raised : 11-Apr-2023				Date Completed : 11-Apr-2023						
Other Details										
Priority :	Normal	ormal QMS Elements R		- SELECT -	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	o SFI :			Verified On :	26/May/2023				
Potential to become a serious accident : Low Recurrence : Low										
Causes										
Lack of training or familiarization, Lack of skills, Lack of proper monitoring										
Corrective Action										
Thorough inspection to be carried out by a responsible officer in order to verify the readiness of the equipment which was previously inadequately attached.										
Preventive Action										
Case will be discussed during the forthcoming Safety Committee Meeting for awareness.										
Applicable Tags										
Root Causes- Management Factors										
Inadequate Procedures / Checklists										
Direct Causes- Unsafe Acts										
Incorrect Use of Equipment or Machinery										

Job Factors								
Inadequate Work Standards								
Personal Factors								
Inadequate Experience								
Follow Up								
On	Ву	Follow Up						
Before & After Pictures								
Before			After					