



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG

Defect ID : 2

Defect Details

During maintenance on SW pump one of engine crew member did not wearing working glove. He used the spaners and the chaine block without protection of his hand

After being observed the engine crew member took out his personal work gloves from his pocket and dressed them to continue the job

Requisition Code :

Categories

| | | | |
|-------------|--------------|---------------|--------|
| Primary : | Near Miss | Vessel Dept : | Engine |
| Secondary : | Improper PPE | Office Dept : | Safety |

Applicable Dates

Date Raised : 15-Jul-2023

Date Completed : 15-Jul-2023

Other Details

| | | | | | |
|---|--------|--------------------|---------------------|---------------|--|
| Priority : | Normal | QMS Elements Ref : | - SELECT - | Verified By : | |
| Show in Monthly Safety Meeting? : | No | SFI : | | Verified On : | |
| Potential to become a serious accident : Medium | | | Recurrence : Medium | | |

Causes

Corrective Action

Traning

Preventive Action

Traning

Applicable Tags

Direct Causes- Unsafe Acts

Failure to Use PPE Properly

Follow Up

| On | By | Follow Up | |
|----|----|-----------|--|
| | | | |

| | | | |
|-------------|---|----------------|--|
| 19/Jul/2023 | Oleg Myronov Staff Code - 10630 - MST | Use proper PPE | |
|-------------|---|----------------|--|

Before & After Pictures

| | |
|---------------|--------------|
| Before | After |
|---------------|--------------|