

Maritec Tanker Management Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 114

Defect Details

Engine room crew was observed not wearing safety helmets and safety glasses while in engine room and carrying out maintenance. The crew was briefed on the important aspects of personal safety and company policy requirements. All have been briefed to ensure adherance of wearing proper PPE while in Engine Room.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Engine			
Secondary :	Improper PPE	Office Dept:	Safety			

Applicable Dates

Date Raised: 16-Feb-2021 Date Completed: 23-Feb-2021

Other Details

Priority :	Normal	QMS Elements Ref :	M. 2.20 - Near Miss Report	Verified By :	Francis Timothy Monteiro
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	03/Jun/2021

Potential to become a serious accident : Low Recurrence : Medium

Causes

Negligence & lack of self discipline.

Corrective Action

All crew members must be reminded to wear proper PPE while at work. PPE is the last line of defence and no one is allowed to take any shortcuts to this.

Preventive Action

Matter must be discussed during next safety meeting with proper emphasis must be given on use of proper PPE for various types of work assigned to crew members.

Applicable Tags

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Personal Factor

Lack of Discipline

Near Miss Details Printed On: 09-Jun-2021 1/2

Lack of Knowledge

Direct Causes- Unsafe Acts

Failure to Use PPE Properly

Personal Factors

Lack of Knowledge

Substandard Acts

Failing to use PPE properly

Follow Up

On By Follow Up

Before & After Pictures

Before After