

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel : Kensington LG					Defect ID : 5				
Defect Details									
DURING SEA PASSAGE ON STB SIDE THE WIND WAS BLOWIG ABEAM AND THE DOOR PUSHED BACK AGAIST THE SHOULDER OF A/B WITHOUT INJURIES .									
Requisition Code :									
Categories									
Primary :	Near Mi	Near Miss		Vessel Dept :		Deck			
Secondary :	Other	Other		Office Dept :		General			
Applicable Dates									
Date Raised : 17-Jul-2023					Date Completed : 17-Jul-2023				
Other Details									
Priority :	Normal	QMS Elements		:	- SELECT -	Verified By :			
Show in Monthly Safety Meeting? :	No	SFI :				Verified On :			
Potential to become a serious accident : Low Recurrence : Low									
Causes									
Corrective Action									
Preventive Action									
Applicable Tags									
Substandard Acts									
Failure to observe basic safety rules									
Follow Up									
On	Ву	Follow Up							
19/Jul/2023	Oleg Myron Staff (10630 - MS	Code -			/ATION OF WEATHER COI TY ON BOARD	NDITION IS			

Before & After Pictures					
Before	After				