

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.										
Vessel : Bahama Blue				Defect ID : 177						
Defect Details										
Paints & Oil samples stored over height of sprinler system										
Requisition Code :										
Categories										
Primary :	Near Mi	Near Miss		Dept :	Deck					
Secondary :	Lack of Leaders	Lack of Supervision / Leadership / Planning		Dept :	Safety					
Applicable Dates										
Date Raised : 20-Jan-2023				Date Completed : 29-Jan-2023						
Other Details										
Priority :	Urgent	QMS Elements Ref :		M. 2.70 - Unsafe Act or Condition	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	13/Mar/2023				
Potential to become	a serious acci	dent : Low		Recurrence : Low						
Causes										
Corrective Action										
Preventive Action										
Applicable Tags										
Root Causes- Personal Factor										
Situational Awareness										
Direct Causes- Unsafe Conditions										
Poor Housekeeping										
Direct Causes- Unsafe Acts										
Improper Securing / Stowage										

Substandard Acts								
Improper Placement								
Substandard Conditions								
Other Unsafe Conditions								
Follow Up								
On	Ву	Follow Up						
27/Jan/2023	Fiacre Fonseca							
Before & After Pictures								
Before			After					

CARGO SAMPLE