



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Viveka

Defect ID : 67

Defect Details

Near Miss Description (Please Mention The Event Chronologically) During inspection in pump room bilges one of the grating was not properly secured in pump room due to which the crewmember slipped & fell down, luckily he was not injured or had any major injury.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Safety

Applicable Dates

Date Raised : 20-Jun-2021

Date Completed : 20-Jun-2021

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	23/Aug/2021
Potential to become a serious accident : Low			Recurrence : Low		

Causes

PERSONAL FACTORS

Corrective Action

PUT GRATING IN PROPER POSITION.

Preventive Action

General briefing was carried out in crew mess room and discussed the potential hazards of slips & falls. Physical injuries, disability involving from sudden slips & falls explained. All crewmembers were advised to work with proper safety & think twice before carrying out any work, personal safety is very important

Applicable Tags**Follow Up**

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before

After