

## **Near Miss Details**

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.						
Vessel : Asphalt Teranga				Defect ID : 142		
Defect Details						
DURING BAD WEATHER A.B WALKED ON DECK CARELESS						
Requisition Code :						
Categories						
Primary :	Near Mi	SS	Vessel Dept :		Deck	
Secondary :	Lack of Situational Awareness		Office Dept :		Safety	
Applicable Dates						
Date Raised : 23-Apr-2023				Date Completed : 23-Apr-2023		
Other Details						
Priority :	Normal	ormal QMS Elements I		- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	No SFI :			Verified On :	26/May/2023
Potential to become a serious accident : Medium Recurrence : Low						
Causes						
LACK OF SAFE PRACTICE.						
Corrective Action						
THE A/B REPRIMANTED, BRIEFED ON THE DANGERS ENCOUNTERED FROM HIS ACTION AND INSTRUCTED NOT TO GO ON DECK WITHOUT PERMISSION AND ALSO TO USE SAFE ACCESS						
Preventive Action						
BEFORE CARRING OUT ANYN JOB / WALKING ON DECK PERMISSION SHOULD BE REQUESTED SO AS TO ENABLE PROPER SUPERVISION						
Applicable Tags						
Follow Up						
On	By Follow Up		ow Up			
Before & After Pictures						
Before			After			