



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

#### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Biskra

Defect ID : 67

#### Defect Details

During commencement of Discharge No.4 COP gland found leaking

Requisition Code :

#### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Safety

#### Applicable Dates

Date Raised : 25-Feb-2022

Date Completed : 03-Mar-2022

#### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : High			Recurrence : Low		

#### Causes

Wear and tear

#### Corrective Action

Pump stopped and Gland tightened. Monitored after starting the pump.

#### Preventive Action

Renewal of gland is planned. During pre operation checks this should be included.

#### Applicable Tags

#### Descriptions

Machinery / Equipment Damage

#### Root Causes- Job Factor

Excessive Wear and Tear

#### Follow Up

On	By	Follow Up	
28/Mar/2022	Nagaraju Rayani   Staff Code - 10431 - C/OFF	Gland renewed. Pics uplodaed after renewal. Working satisfactory	
03/Mar/2022	Nawin Khaware	Submit evidence/photographs once gland packing has been renewed and tested to be found working satisfactory.	

**Before & After Pictures**

Before	After
--------	-------



