



# Maritec Tanker Management Private Limited

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 309

### Defect Details

CREW GOT DOWN FROM THE CATWALK USING THE DECK STEP LADDER AND CARRING A CAN WITH PAINT IN ONE HAND AND PAINT ROLLER IN OTHER HAND. ONE HAND GRIP DID NOT FOLLOWED.  
ADVISED CREW TO FOLLOW ONE HAND GRIP.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Procedures not Followed	Office Dept :	General

### Applicable Dates

Date Raised : 26-Aug-2023

Date Completed : 26-Aug-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	06/Oct/2023
Potential to become a serious accident : Low			Recurrence : Low		

### Causes

Not following safe working practices.

### Corrective Action

ADVISED CREW TO FOLLOW ONE HAND GRIP

### Preventive Action

Training given to crew about the importance of keeping one hand grip.

### CONTRIBUTING FACTORS

#### Root Causes- Personal Factor

Situational Awareness

#### Substandard Acts

Failure to follow procedure

**Follow Up**

<b>On</b>	<b>By</b>	<b>Follow Up</b>	
-----------	-----------	------------------	--

**Before & After Pictures**

<b>Before</b>	<b>After</b>
---------------	--------------