Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:
01) Please do not mention any names in the near miss report.
02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG	Defect ID : 8

Defect Details

During sea passage was observed that Hook on Stbd Hose handling Crane is not secured and freely mooving different directions.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Procedures not Followed	Office Dept :	Safety

Applicable Dates

Date Raised : 26-Jul-2023	Date Completed : 03-Aug-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	11/Aug/2023

Potential to become a serious accident : Low	Recurrence : Medium

Causes

Corrective Action

Preventive Action

CONTRIBUTING FACTORS

Descriptions

Damage to Vessel

Injury

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Personal Factor

Lack of Skill

Job Factors
Inadequate Supervision

Personal Factors
Lack of Skill

Follow Up

On	By	Follow Up	
03/Aug/2023	Oleg Myronov Staff Code - 10630 - MST	Discussed on morning job plan meeting. Remind crew good work practice on board. Pointed that after compleation of job all equipment should be secured properly.	
02/Aug/2023	Nawin Khaware	Provide complete fields of causes, corrective action and preventive action plans. Just by writing one liner details doesn't suffice any purpose of reporting. If you consider this as near miss then carry out complete investigation and establish causes, CA & PA. Once done then select applicable tags by pressing on drop down list and select the applicable tags from here and then resubmit.	

Before & After Pictures

Before	After