



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
 Office File No : N/A  
 Form No : N/A  
 Issue : N/A  
 Revision : N/A  
 Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara	Defect ID : 82
-------------------	----------------

**Defect Details**

During Night round Near the MGO Safety Filter, it was observed to have some oil spilled post cleaning the filter, Considering the high temperature in the vicinity, immediately Oil was cleaned, area secured and Entire Team was explained regarding the risk involved.

Requisition Code :

**Categories**

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Situational Awareness	Office Dept :	Safety

**Applicable Dates**

Date Raised : 28-Jul-2023	Date Completed : 28-Jul-2023
---------------------------	------------------------------

**Other Details**

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Low		

**Causes****Corrective Action****Preventive Action****Applicable Tags****Descriptions**

Fire / Explosion

**Root Causes- Job Factor**

Inadequate Work Standards

**Follow Up**

On	By	Follow Up
----	----	-----------

Before & After Pictures

Before

After