

## **Near Miss Details**

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.						
Vessel: Bahama Blue				Defect ID : 103		
Defect Details						
While on his way down from the bridge, 2nd Officer nearly hit when other crew suddenly open the door from 2nd deck to make his way also to the stairway.						
Requisition Code :						
Categories						
Primary :	Near Mi	Near Miss		Dept :	Deck	
Secondary :		Inadequte Engineering /Design		Dept :	Safety	
Applicable Dates						
Date Raised : 28-Mar-2022				Date Completed : 29-Mar-2022		
Other Details						
Priority :	Normal	QMS Elements Ref :		- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	
Potential to become a serious accident : Medium Recurrence : Medium						
Causes						
The door opening is on close proximity of the stairway.						
Corrective Action						
Advised all crew member to be aware and open any door slowly in order to not to hit other crew on other side and plan to make poster saying "CAUTION PLEASE, OPEN THE DOOR SLOWLY ANYBODY MIGHT BE PASSING N THE STAIRWAY" and post it on every door.						
Preventive Action						
Poster posted in every door.						
Applicable Tags						
Follow Up						
On	Ву	By Follow		/ Up		
Before & After Pictures						

