

Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bahama Blue Defect ID: 103

Defect Details

While on his way down from the bridge, 2nd Officer nearly hit when other crew suddenly open the door from 2nd deck to make his way also to the stairway.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Inadequte Engineering /Design	Office Dept:	Safety			

Applicable Dates

Date Raised: 28-Mar-2022 Date Completed: 29-Mar-2022

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	
Determinate the control of the contr		Danish Madisus			

Potential to become a serious accident: Medium Recurrence: Medium

Causes

The door opening is on close proximity of the stairway.

Corrective Action

Advised all crew member to be aware and open any door slowly in order to not to hit other crew on other side and plan to make poster saying "CAUTION PLEASE, OPEN THE DOOR SLOWLY ANYBODY MIGHT BE PASSING N THE STAIRWAY" and post it on every door.

Preventive Action

Poster posted in every door.

Applicable Tags

Follow Up

On	Ву	Follow Up	

Before & After Pictures

Near Miss Details Printed On: 06-Apr-2022 1/2

Before After



