

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.								
Vessel : Asphalt Teranga				Defect ID : 146				
Defect Details								
BEFORE DISCHARGING AT THE PORT A SURVEYOR DURING TANK MEASURING AND ULLAGING ALTHOUGH HE WAS CARRYING SAFETY GOGGLES AND GLOVES .BUT HE DIDN'T WEAR. CHIEF MATE THEREUPON ADVISE HIM TO WEAR IT'S AND ALWAYS TO BE FOLLOW SAFETY INSTRUCTIONS ON BOARD.								
Requisition Code :								
Categories								
Primary :	Near Miss		Vessel Dept :		Deck			
Secondary :	Procedu	Safe Working Procedures not Followed		Dept :	Safety			
Applicable Dates								
Date Raised : 28-May-2023				Date Completed : 06-Jun-2023				
Other Details								
Priority :	Normal	ormal QMS Elements F		- SELECT -	Verified By :	Nawin Khaware		
Show in Monthly Safety Meeting? :	No	o SFI :			Verified On :	19/Jun/2023		
Potential to become a serious accident : Medium Recurrence : Low								
Causes								
LACK OF SAFE PRACTICE.								
Corrective Action								
CHIEF OFFICER IN ADDITION GAVE AFTER PROPER INSTRUCTIONS TO CREW TO FOLLOW THE SAFETY INSTRUCTIONS WHEN ULLAGING AND TANK MEASURING.								
Preventive Action								
CREW TO ALWAYS USE PROPER PPE DURING CARGO OPERATION								
Applicable Tags								
Root Causes- Personal Factor								
Lack of Discipline								
Lack of Knowledge								
Direct Causes- Unsafe Acts								

Failure to Follow Rules and Regulations

Personal Factors

Lack of Knowledge

Substandard Acts

Failure to observe basic safety rules

Follow Up						
On	Ву	Follow Up				
19/Jun/2023	Nawin Khaware	Each persons visiting onboard MUST compy with company's safety guidelines. Visitors must wear proper PPE while coming onboard. His PPE gears must be checked at the time of his boarding.				

Before & After Pictures					
Before	After				