

Near Miss Details

Guidance: 01) Please do not ment 02) The confidentiality v 03) NOTE: ADDITIONA	ion any names i vill be maintaine L INFORMATIC	n the near miss repo d by removing the n NN IF REQUIRED TO	ort. ame of the D BE ADDI	vessel when the report is circu ED IN A SEPARATE SHEET AI	lated to the different	vessels in the fleet. THIS REPORT.				
Vessel : Bitu Atlantic				Defect ID : 265						
Defect Details										
Crew member found cleaning lube oil spare filter without wearing face shield.										
Requisition Code :										
Categories										
Primary :	Near Mi	Near Miss		Dept :	Engine					
Secondary :	Procedu	Safe Working Procedures not Followed		Dept :	Safety					
Applicable Dates										
Date Raised : 30-Jan-2023				Date Completed : 01-Feb-2023						
Other Details										
Priority :	Normal	al QMS Elements R		- SELECT -	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	01/Feb/2023				
Potential to become	a serious accio	dent : Low	Recurrence : Low							
Causes										
Carelessness										
Corrective Action										
Instructed to all crew member to use always proper PPE.										
Preventive Action										
Proper briefing carried out for all engine crew.										
Applicable Tags										
Root Causes- Job Factor										
Inadequate Work Standards										
Root Causes- Personal Factor										
Lack of Knowledge										
Direct Causes- Unsafe Acts										

Failure to Follow Rules and Regulations								
Job Factors								
Inadequate Supervision								
Personal Factors								
Lack of Knowledge								
Substandard Acts								
Failure to observe basic safety rules								
Follow Up								
On	Ву	Follow Up						
01/Feb/2023	Nawin Khaware	Each crew memb safety and entire officer to ensure j	er must take care of their personal jobs must be supervised by senior obs are completed safely.					
Before & After Pictures								
Before			After					