



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 139

**Defect Details**

DURING MOORING OPERATION IT WAS OBSERVE THAT STBD MOORING WINCH ON ELECTRONIC ACTUATOR NOT ABLE TO RETURN TO ZERO POSITION BY IT SELF.

Requisition Code :

**Categories**

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

**Applicable Dates**

Date Raised : 30-Mar-2023

Date Completed :

**Other Details**

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Low		

**Causes**

ELECTRONIC ACTUATOR FAILURE

**Corrective Action**

KEPT SWITCH THE ELECTRONIC POWER OFF DURING MOORING OPERATION AS ADDITION SELF CONTROL.

**Preventive Action**

CARYY OUT REPAIR OF EQUIPMENT AND FIX THE ISSUE.

**Applicable Tags****Root Causes- Job Factor**

Inadequate Tools and Equipment

**Direct Causes- Unsafe Conditions**

Defective Equipment, Machinery or Tools

**Follow Up**

On	By	Follow Up	
19/Jun/2023	Nawin Khaware	Pls update here the latest status, provide either photographs/records etc.. if repair has been completed.	
26/May/2023	Nawin Khaware	I can't see any updates from vessel side, kindly advise if the issues has been resolved.	
21/Apr/2023	Nawin Khaware	Pls advise the present status of equipment.	
13/Apr/2023	Nawin Khaware	What is the present status of equipments.	

Before & After Pictures	
Before	After