



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 110	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

During round it was observed that one of the condemn hose was lying on poop deck without proper tagging on it as "Not to be used"

Requisition Code :

Categories

Primary :	Garbage	Inspector - Internal :	Wasi Ahmad	Vessel Dept :	Deck
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Safety
		Inspection Date :	01-Oct-2020		

Applicable Dates

Date Raised : 01-Oct-2020	ETC : 08-Oct-2020	Date Completed : 01-Oct-2020
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Ops Suptd	Verified By : Wasi Ahmad
Display in Daily Meeting? : No	SFI :	Verified On : 24/Nov/2020

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
02/Nov/2020	Wasi Ahmad		

Before & After Pictures

Before	After
--------	-------



File not found !



File not found !