



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 96	NCR # :	Is NCR ? : No
----------------------	----------------	---------	---------------

Defect Details

Mooring winch drum – direction of drum rotation is not marked, Arrow marking for showing direction of movement to be marked on drum with clear indication Heave/or lower.

Requisition Code :

Categories

Primary :	Missing	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Miscellaneous	Inspector External :		Office Dept :	General
		Inspection Date :	06-Jan-2022		

Applicable Dates

Date Raised : 06-Jan-2022	ETC : 15-Jan-2022	Date Completed : 23-Feb-2022
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
02/Feb/2022	Muddassar Jafri		

Before & After Pictures

Before	After
--------	-------

