



Maritec Tanker Management

Defect List Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 98	NCR # :	Is NCR ? : No
----------------------	----------------	---------	---------------

Defect Details

Signs of rust marks could be sighted on main deck area, Requiring deck maintenance and painting. – Closure by 10 Mar 2022.

Requisition Code :

Categories

Primary :	Missing	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Miscellaneous	Inspector External :		Office Dept :	General
		Inspection Date :	06-Jan-2022		

Applicable Dates

Date Raised : 06-Jan-2022	ETC : 10-Mar-2022	Date Completed : 02-Mar-2022
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 26/Apr/2022

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
26/Apr/2022	Nawin Khaware	Based on photographic evidence submitted by the vessel, this observation can be considered as closed now.	
02/Feb/2022	Muddassar Jafri		

Before & After Pictures

Before	After
--------	-------