

Before

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Vessel: Morbihan Defect ID: NCR#: Is NCR ?: No **Defect Details** During safety around was found noisely working W/H sea water cooling p/p, after stoping pump was found leakege from shaft seal. Replace bearing for electrical motor & shaft seal have to be request by Reqsn Num: MORB-SOT-V230182; Title: Spare part seal kit & bearings for electrical motor. Requisition Code: Categories Primary: E/R Inspector - Internal: Vessel Dept: **Engine** Machinery Auxiliary Equipment Inspector External: Office Dept: Purchase Secondary: Inspection Date : **Applicable Dates** Date Raised: 07-Jul-2023 ETC: 14-Jul-2023 Date Completed: Other Details Priority: Normal Assigned By: Vessel Verified By: Display in Daily Meeting? : No SFI: Verified On: Causes **Corrective Action Preventive Action Applicable Tags** Follow Up **Follow Up** On By **Before & After Pictures**

Defect List Details Printed On: 17-Jul-2023 1/1

After