

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

| Vessel : Mor | bihan | Defect ID |): 93 | | NCR # : | | Is NCR ?: No | | |
|--|------------------------|------------------------|---------------------|-----------|---------|------------------|--------------|-------|-----|
| Defect Details | | | | | | | | | |
| During safety around was found noisely working W/H sea water cooling p/p, after stoping pump was found leakege from shaft seal. Replace bearing for electrical motor & shaft seal have to be request by Reqsn Num: MORB-SOT-V230182; Title: Spare part seal kit & bearings for electrical motor. | | | | | | | | | |
| Requisition Code: | | | | | | | | | |
| Categories | | | | | | | | | |
| Primary : | E/R Machinery | Inspector - Internal : | | | | Vessel Dept: | | Engin | e |
| Secondary : | Auxiliary Equipment | Inspe | ctor External : | | | Office Dept: | | Purch | ase |
| | | Inspe | ction Date : | | | | | | |
| Applicable Dates | | | | | | | | | |
| Date Raised: 07-Jul-2023 | | | ETC: 14-Jul-2023 | | | Date Completed : | | | |
| Other Details | | | | | | | | | |
| Priority : Normal | | | Assigned By: Vessel | | | Verified By : | | | |
| Display in Daily Meeting? : No | | | SFI: | | | Verified On: | | | |
| Causes | | | | | | | | | |
| Corrective Action | | | | | | | | | |
| Preventive Action | | | | | | | | | |
| Applicable Tags | | | | | | | | | |
| Follow Up | | | | | | | | | |
| On | Ву | | Follow Up | Follow Up | | | | | |
| Before & After Pictures | | | | | | | | | |
| Before | | | | | After | | | | |

Defect List Details Printed On: 17-Jul-2023 1/1