

Before & After Pictures

Before


Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Atlantic Defect ID: 76 NCR#: Is NCR ?: No **Defect Details** 6. In company Policies and Procedure posters posted on bridge and common spaces GM sign were missing. Requisition Code: Categories Primary: Others Inspector - Internal: Wasi Ahmad Vessel Dept: Deck Office Dept: Notices and Inspector External: Safety Secondary: **Posters** 11-Mar-2020 Inspection Date : **Applicable Dates** ETC: 31-Mar-2020 Date Raised: 11-Mar-2020 Date Completed: 29-Mar-2020 Other Details Priority: Normal Assigned By: Ops Suptd Verified By: Wasi Ahmad Display in Daily Meeting? : No SFI: Verified On: 02/Nov/2020 Causes **Corrective Action Preventive Action Applicable Tags** Follow Up On Ву **Follow Up** 30/Mar/2020 New received posters with GM signature laminated and Petru Ciobanu Petrescu
 old ones replaced. Staff Code - 10050 - MST

Defect List Details Printed On: 03-Nov-2020 1/2

After



File not found!

Defect List Details Printed On: 03-Nov-2020 2/2