

Maritec Tanker Management

Defect List Details

| Vessel: Bitu Atlantic | | Defect ID: 266 | | NCR # | NCR # : | | Is NCR ? : No | |
|--|----------------------|----------------|----------------------|-------|---------|------------------------------|---------------|--|
| Defect Details | | | | | | | | |
| Main sea water pump elect motor send to shore for rewinding. | | | | | | | | |
| Requisition Code : | | | | | | | | |
| Categories | | | | | | | | |
| Primary : | E/R Machinery | Inspec | tor - Internal: | | | | : Engine | |
| Secondary : | Electrical equipment | Inspec | tor External : | | | Office Dept | : Technical | |
| | | Inspec | tion Date : | | | | | |
| Applicable Dates | | | | | | | | |
| Date Raised : 15-Feb-2023 | | | ETC : 22-Feb-2023 | | | Date Completed : 15-Apr-2023 | | |
| Other Details | | | | | | | | |
| Priority : Normal | | | Assigned By : Vessel | | | Verified By : | | |
| Display in Daily Meeting? : No | | | SFI : | | | Verified On : | | |
| Causes | | | | | | | | |
| Corrective Action | | | | | | | | |
| Preventive Action | | | | | | | | |
| Applicable Tags | | | | | | | | |
| Follow Up | | | | | | | | |
| On | Ву | | Follow Up | | | | | |
| Before & After Pictures | | | | | | | | |
| Before | | | | After | | | | |







