

## Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Atlantic		Defect ID: 266		NCR # :		IS NCR ? : No	
Defect Details							
Main sea water pump elect motor send to shore for rewinding.							
Requisition Code:							
Categories							
Primary :	E/R Machinery				Vessel Dept:	Engine	
Secondary :	Electrical equipment	Insped	ctor External :		Office Dept:	Technical	
		Inspec	ction Date :				
Applicable Dates							
Date Raised: 15-Feb-2023			ETC: 22-Feb-2023		Date Completed: 15-Apr-2023		
Other Details							
Priority : Normal			Assigned By: Vessel		Verified By :		
Display in Daily Meeting? : No			SFI:		Verified On:		
Causes							
Corrective Action							
Preventive Action							
Applicable Tags							
Follow Up							
On	Ву		Follow Up				
Before & After Pictures							
Before				After			

Defect List Details Printed On: 21-Jun-2023 1/2







