



## Maritec Tanker Management

### Defect List Details

Ship File No : N/A  
 Office File No : N/A  
 Form No : N/A  
 Issue : N/A  
 Revision : N/A  
 Rev Date : N/A

Vessel : Bitu Express	Defect ID : 47	NCR # :	Is NCR ? : No
-----------------------	----------------	---------	---------------

#### Defect Details

Post installation of Mewis Duct, Ship Maneuvering characteristics to be verified.

Requisition Code :

#### Categories

Primary :	Others	Inspector - Internal :	Rakesh Kumar	Vessel Dept :	Deck
Secondary :	Others	Inspector External :		Office Dept :	Safety
		Inspection Date :	17-Feb-2020		

#### Applicable Dates

Date Raised : 17-Feb-2020	ETC : 24-Feb-2020	Date Completed : 12-May-2020
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Follow Up

On	By	Follow Up	
12/May/2020	Marin Panait	On departure from Malta OPL 11-05-2020, vessel check manoeuvring characteristics, with the vessel in loaded condition.	<a href="#">Link1</a> <a href="#">Link2</a> <a href="#">Link3</a> <a href="#">Link4</a> <a href="#">Link5</a> <a href="#">Link6</a> <a href="#">Link7</a> <a href="#">Link8</a> <a href="#">Link9</a> <a href="#">Link10</a> <a href="#">Link11</a>

Before & After Pictures

Before

After