

## Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu River		Defect ID : 23			NCR#:		Is NCR ? : No	
Defect Details								
Rag were lying all around the changing room								
Requisition Code:								
Categories								
Primary :	Hygeine Inspe		ector - Internal :		as Fernandes Vessel De		pt :	Deck
Secondary :	Miscellaneous	Inspect	ctor External :			Office Dep	ot :	Safety
		Inspect	etion Date : 2		-Mar-2023			
Applicable Dates								
Date Raised : 20-Mar-2023			ETC: 19-Apr-2023			Date Completed: 01-Apr-2023		
Other Details								
Priority : Urgent			Assigned By: HSQE Suptd			Verified By :		
Display in Daily Meeting? : No			SFI:			Verified On:		
Causes								
Corrective Action								
Preventive Action								
Applicable Tags								
Follow Up								
On	Ву		Follow Up					
27/Mar/2023	Muddas	sar Jafri						
Before & After Pictures								
Before				After				

Defect List Details Printed On: 17-Jul-2023 1/2



