



## Maritec Tanker Management

### Defect List Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River	Defect ID : 21	NCR # :	Is NCR ? : No
---------------------	----------------	---------	---------------

#### Defect Details

BT Room Vent mesh to clean and de rust

Requisition Code :

#### Categories

Primary :	Others	Inspector - Internal :	Judas Fernandes	Vessel Dept :	Deck
Secondary :	Vessel Housekeeping	Inspector External :		Office Dept :	Safety
		Inspection Date :	20-Mar-2023		

#### Applicable Dates

Date Raised : 20-Mar-2023	ETC : 19-Apr-2023	Date Completed : 28-Mar-2023
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Follow Up

On	By	Follow Up	
27/Mar/2023	Muddassar Jafri		

#### Before & After Pictures

Before	After
--------	-------

