



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 142	NCR # :	Is NCR ? : No
-----------------	-----------------	---------	---------------

Defect Details

Mooring winch pumps forward- oil leaks from fittings to be rectified .

Requisition Code :

Categories

Primary :	Dk Machinery	Inspector - Internal :	Kamlesh Jalori	Vessel Dept :	Engine
Secondary :	Hydraulic Machinery For Mooring Winch	Inspector External :		Office Dept :	Technical
		Inspection Date :	21-Jan-2023		

Applicable Dates

Date Raised : 21-Jan-2023	ETC : 08-Feb-2023	Date Completed :
---------------------------	-------------------	------------------

Other Details

Priority : Normal	Assigned By : Tech Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
31/Jan/2023	Kamlesh Jalori		

Before & After Pictures

Before	After
--------	-------