

Before

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Viveka		Defect ID: 58			NCR # :			Is NCR ?: No		
Defect Details										
SOPEP Locker - Access to SOPEP items was not clear and found lots of loose items on the floor in way of items. SOPEP locker should be kept clear from all obstructions.										
Requisition Code:										
Categories										
Primary :	Others	Inspect	ctor - Internal :		win Khaware	Vessel Dept:		Deck		
Secondary :	Oil Spill Contigency Equip	Inspector External :				Office Dept:		Safety		
		Inspect	Inspection Date :		May-2021					
Applicable Dates										
Date Raised: 21-May-2021			ETC: 21-Jun-2021			Date Completed: 07-Jun-2021				
Other Details										
Priority : Normal			Assigned By: HSQE Suptd			Verified By :				
Display in Daily Meeting? : No			SFI:			Verified On:				
Causes										
Corrective Action										
Preventive Action										
Applicable Tags										
Follow Up										
On	n By			Follow Up						
01/Jun/2021 Nawin Khaware										
Before & After Pictures										

Defect List Details Printed On: 09-Jun-2021 1/2

After



