

Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Defect List Details

Vessel : Mun	nbai Office E	Defect ID:	1		NCR # :		Is NC	R?: No	
Defect Details									
Office emergency escape door - "EXIT" marking was deteriorated and requiring renewals.									
Requisition Code :									
Categories									
Primary :	Others	Inspecto	ctor - Internal:		win Khaware	Vessel De	pt:	Deck	
Secondary :	Others	Inspector External :				Office Dep	t :	Safety	
		Inspection Date : 27		27-	-Dec-2021				
Applicable Dates									
Date Raised : 27-Dec-2021			ETC: 03-Jan-2022			Date Completed : 21-Jan-2022			
Other Details									
Priority : Normal			Assigned By : HSQE Suptd			Verified By : Nawin Khaware			
Display in Daily Meeting? : No			SFI :			Verified On : 04/Apr/2022			
Causes									
Corrective Action									
Preventive Action									
Applicable Tags									
Root Causes- Job Factor									
Excessive Wear and Tear									
Follow Up									
On	Ву	By Follow Up							
04/Apr/2022	recently painted he					s peeled off from the door as it was ence leading to missing off required s renewed and check process on regular n in place now.			
16/Mar/2022	Muddassa								
Before & After Pictures									
Before					After				



