

Maritec Tanker Management Defect List Details

Ship File No: N/A
Office File No: N/A
Form No: N/A
Issue: N/A
Revision: N/A
Rev Date: N/A

Vessel: Bitu Atlantic	Defect ID: 165	NCR # :	Is NCR ?: No

Defect Details

During E/R rounds it was observed that lots of old valves/pipelines/fittings are lying behind the M/E Cyl. oil storage tank which poses hazard to vessel as items might shift from it's stowed position leading to damaging various machinery in the vicinity. Suggest to discard all these items at first available opportunity.

Requisition Code:

Categories					
Primary :	Others	Inspector - Internal:	Nawin Khaware	Vessel Dept:	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept:	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised: 27-Sep-2021 ETC: 25-Nov-2021 Date Completed: 13-Jan-2022

Other Details		
Priority : Normal	Assigned By: HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI:	Verified On:

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	Ву	Follow Up	
31/Dec/2021	Nawin Khaware	Please upload all the evidence to confirm the items are actioned from vessel side.	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before	After

Defect List Details Printed On: 04-Apr-2022 1/2



