



## Maritec Tanker Management

### Defect List Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Biskra	Defect ID : 83	NCR # :	Is NCR ? : No
-----------------	----------------	---------	---------------

#### Defect Details

Co2 storage cabinet for paint locker- hinge broken - to repair

Requisition Code :

#### Categories

Primary :	Fire	Inspector - Internal :	Kamlesh Jalori	Vessel Dept :	Deck
Secondary :	Paint Store Fire	Inspector External :		Office Dept :	Technical
		Inspection Date :	30-Jul-2022		

#### Applicable Dates

Date Raised : 30-Jul-2022	ETC : 30-Aug-2022	Date Completed : 24-Aug-2022
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : Tech Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Root Causes- Job Factor

Excessive Wear and Tear

#### Root Causes- Management Factors

Inadequate Resources for Operations

#### Root Causes- Personal Factor


Others

#### Follow Up

On	By	Follow Up	
22/Aug/2022	Kamlesh Jalori		

Before & After Pictures

Before



After

