

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Express	Defect ID: 273	NCR # :	Is NCR ? : No
VC33CI . Dita Express	Delectib . 270	NOIC # .	13 11010 : . 110

Defect Details

No Comparison carried out for SAAB Radar gauges with Manual Gauging.

Requisition Code:

Categories					
Primary :	Records	Inspector - Internal:	Fiacre Fonseca	Vessel Dept:	Deck
Secondary :	Miscellaneous	Inspector External :		Office Dept:	Operations
		Inspection Date :	31-Aug-2022		

Applicable Dates

Date Raised: 31-Aug-2022 ETC: 30-Oct-2022 Date Completed: 24-Sep-2022

Other Details

Priority: Normal Assigned By: Ops Suptd Verified By: Fiacre Fonseca

Display in Daily Meeting? : No SFI: Verified On : 12/Oct/2022

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	Ву	Follow Up	
09/Oct/2022	George Veliu Staff Code - 10329 - MST	Comparison done between SAAB and Manual Guaging	
14/Sep/2022	Fiacre Fonseca		

Before & After Pictures

Before	After

Defect List Details Printed On: 17-Jul-2023 1/2



