

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic Defect ID : 148 NCR # : Is NCR ? : No

Defect Details

Cargo Hose rest on ship side - to paint black

Requisition Code:

Categories						
Primary :	Cargo	Inspector - Internal:	Vikram Puri	Vessel Dept:	Deck	
Secondary :	Miscellaneous	Inspector External :		Office Dept:	RAME	
		Inspection Date :	31-Jul-2021			

Applicable Dates

Date Raised: 31-Jul-2021 ETC: 08-Sep-2021 Date Completed: 31-Aug-2021

Other Details

Priority: Normal Assigned By: Tech Suptd Verified By:

Display in Daily Meeting? : No SFI: Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Other Job Factors

Follow Up

On	Ву	Follow Up	
31/Aug/2021	Kamlesh Jalori		

Before & After Pictures

Before After

Defect List Details Printed On: 04-Apr-2022 1/2



