



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 144	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Marking of pipe line on deck

Requisition Code :

Categories

Primary :	Fittings	Inspector - Internal :	Vikram Puri	Vessel Dept :	Deck
Secondary :	Deck Pipelines	Inspector External :		Office Dept :	RAME
		Inspection Date :	31-Jul-2021		

Applicable Dates

Date Raised : 31-Jul-2021	ETC : 07-Sep-2021	Date Completed : 06-Sep-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Tech Suptd	Verified By : Kamlesh Jalori
Display in Daily Meeting? : No	SFI :	Verified On : 22/Oct/2021

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Other Job Factors

Follow Up

On	By	Follow Up	
27/Aug/2021	Kamlesh Jalori		

Before & After Pictures

Before	After
--------	-------

