



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 13-Apr-2023		
Location : DECK		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : Started the Chipping Gun for chipping on deck, the jubilee clip connection made on the coupling and air hose was loosen up. The hose came out from the coupling due to air pressure and the air hose hit on crew healmet.		
Was action taken at the time? :	Yes	Close the air valve. Tighten the jubilee clip and make sure its full tight for use.
Was work stopped? :	Yes	Close the air valve. Tighten the jubilee clip and make sure its full tight for use.
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : This incident is very dangerous, Kindly ensure all power tool connections are checked and verified		
Date Reviewed by DPA : 20-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		