

Vessel - Bitu Atlantic (IMO: 9382085)

Inspection Type 006 - Vessel Inspection Report

Inspection Date 05 Sep 2019

Inpector JudaS Xavier Fernandes

From Port Yalova
To Port Yalova

Hours Onboard

Avg Audit Findings 57 %
No of NCRs 0
No of Observation 10



Crew Interview & Attendance Record

Staff Name	Rank	Remarks	Signature
------------	------	---------	-----------

Auditor Signature

JudaS Xavier Fernandes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.01 - External Condition - Propeller

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.02 - External Condition - Rudder

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.03 - External Condition - Ship's name and Port of Registry

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.04 - External Condition - Hull - Topside area

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.05 - External Condition - Hull - Boot top area

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.06 - External Condition - Draft marks

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.07 - External Condition - Plimsoll mark

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.01 - Part I - External Condition

Question 01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.01 - Decks - Accommodation Ladders - Platform / Wires / Motor

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.02 - Decks - Ships name - bridge wings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.03 - Decks - MOT Gangway

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.04 - Decks - Railings and Bulwark

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.05 - Decks - Superstructure / Funnel

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.06 - Decks - Forecastle deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.07 - Decks - Windlass

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.08 - Decks - Anchor / cables - port and STBD

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.09 - Decks - Mooring ropes and wires

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.10 - Decks - Mooring winches on forecastle deck

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.11 - Decks - Deck Light masts and fittings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.12 - Decks - Forward mast

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.13 - Decks - Forward and aft Talk back system

Answer Detail Grade - No

Answer Remark NA



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.14 - Decks - Main deck plating

Answer Detail Grade - No

Answer Remark DERUSTING AND PAINTING REQUIRED ON MAIN DECK

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15a - Pipelines - Ballast

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15b - Pipelines - Cargo

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15c - Pipelines - Steam/Thermal Oil

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15d - Pipelines - Fire

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15e - Pipelines - Foam

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15f - Pipelines - Hydraulic

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15g - Pipelines - Electrical conduit

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.15h - Pipelines - Insulation

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.16 - Decks - Cargo manifold and drip tray/Various Pressure & Temp. gauges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.17 - Decks - Air pipes / Sounding pipes / Filling pipes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.18 - Decks - Cranes / Derricks and associated loose gear, motors and winches

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.19 - Decks - Mooring winches on main deck

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.20 - Decks - Aft deck / poop deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.21 - Decks - Mooring winches on aft / poop deck

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.22 - Decks - Condition of spare propeller, anchor

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.23 - Decks - Monkey island deck plating

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.24 - Decks - Main mast and fittings

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.25a - Tugs - Towing winch

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.25b - Tugs - Deck rollers

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.25c - Tugs - Fenders

Answer Detail Grade - No

Answer Remark NA



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.25d - Tugs - Aft control station

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26a - Tankers - Cargo tank domes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26b - Tankers - Ballast tank openings

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26c - Tankers - Deck valves including stub pieces

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26d - Tankers - Ullage ports / vapor locks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26e - Tankers - Level gauging systems

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26f - Tankers - PV valves / air vents / Mast risers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.26g - Tankers - Deck Seal / PV Breaker on IG line

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.02 - Part II - Decks

Question 01.02.27 - Deck Lighting and Emergency Lighting

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.01 - Internal Hull Structure - Fore peak store(s)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.02 - Internal Hull Structure - Paint room including its fixed fire extinguishing system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.03 - Internal Hull Structure - Fore peak tank

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.04 - Internal Hull Structure - Chain lockers and void spaces

Answer Detail Grade - No

Answer Remark NOT INSPECTED

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.05 - Internal Hull Structure - For'd hydraulic room for mooring winches

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.06 - Internal Hull Structure - Cargo tank No 1 C/P/S(includes insulation)

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.07 - Internal Hull Structure - Cargo tank No 2 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.08 - Internal Hull Structure - Cargo tank No 3 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.09 - Internal Hull Structure - Cargo tank No 4 C/P/S(includes insulation)

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.10 - Internal Hull Structure - Cargo tank No 5 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.11 - Internal Hull Structure - Cargo tank No 6 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.12 - Internal Hull Structure - Cargo tank No 7 C/P/S(includes insulation)

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.13 - Internal Hull Structure - Cargo tank No 8 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.14 - Internal Hull Structure - Cargo tank No 9 C/P/S(includes insulation)

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.15 - Internal Hull Structure - Water ballast topside tanks

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.16 - Internal Hull Structure - Water ballast D.B. tanks

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.17 - Internal Hull Structure - Slop tanks

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.18 - Internal Hull Structure - Butterworthing machines

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.19 - Internal Hull Structure - COW system

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.20 - Internal Hull Structure - IG system and valves

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.21 - Internal Hull Structure - Deep tanks outside E/R

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.22 - Internal Hull Structure - Cofferdams outside E/R

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.23 - Internal Hull Structure - Pipe tunnel

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.24 - Internal Hull Structure - Aft peak stores

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.26 - Internal Hull Structure - E/R D.B. tanks

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.27 - Internal Hull Structure - E/R bunker tanks

Answer Detail Grade - No

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.03 - Part III - Internal Hull Struc

Question 01.03.28 - Internal Hull Structure - Cofferdams inside E/R

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.01 - Mast Houses/ Midship Stores - Internal area

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.02 - Mast Houses / Midship Stores - Hydraulic motors

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.03 - Mast Houses / Midship Stores - Electric panels

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.04 - Mast Houses / Midship Stores - Doors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.05 - Mast Houses / Midship Stores - Top decks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.06 - Mast Houses / Midship Stores - Ladders

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.07 - Mast Houses / Midship Stores - Fittings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.04 - Part IV - Mast Houses / Midsh

Question 01.04.08 - Mast Houses / Midship Stores - House keeping

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.01 - Cargo Pump Room - Housekeeping and general condition

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.02 - Cargo Pump Room - Cargo pumps / Ballast pumps/Pressure & Temp. gauges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.03 - Cargo Pump Room - Stripper pump / Cargo eductors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.04 - Cargo Pump Room - Vacuum stripping system

Answer Detail Grade - No

Answer Remark NA



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.05 - Cargo Pump Room - Pipe lines/Insulations

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.06 - Cargo Pump Room - Bilges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.07 - Cargo Pump Room - Ventilation/Bottom Flap Operation from outside P/P Room

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.08 - Cargo Pump Room - Ladders, Platforms and gratings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.09 - Cargo Pump Room - Bilge Alarm(s)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.10 - Cargo Pump Room - Butterworth heater

Answer Detail Grade - No

Answer Remark NA



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.11 - Cargo Pump Room - Lighting

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.12 - Cargo Pump Room - Hydraulic and pneumatic valves and pipelines in p/p room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.05 - Part V - Cargo Pump Room

Question 01.05.13 - Cargo Pump Room - Gas detection system

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.01 - Accommodation Spaces - Companionways on open decks

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.02 - Accommodation Spaces - Vent flaps - natural and forced

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.03 - Accommodation Spaces - Accommodation decks

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.04 - Accommodation Spaces - Doors - Watertight / Weather tight

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.05 - Accommodation Spaces - Deck lighting and cable fitting

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.06 - Accommodation Spaces - Railings

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.07 - Accommodation Spaces - Companionways inside accommodation

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.08 - Accommodation Spaces - Alleyways

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.09 - Accommodation Spaces - Lighting inside alleyways

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.10 - Accommodation Spaces - Galley

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.11 - Accommodation Spaces - Pantries

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.12 - Accommodation Spaces - Provision rooms

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.13 - Accommodation Spaces - Fridge rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.14 - Accommodation Spaces - Laundries and dry rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.15 - Accommodation Spaces - Hobby room

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.16 - Accommodation Spaces - Crew Wash rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.17 - Accommodation Spaces - Crew change rooms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.18 - Accommodation Spaces - Crew cabins

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.19 - Accommodation Spaces - Officers cabins

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.20 - Accommodation Spaces - Officers Mess room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.21 - Accommodation Spaces - Officers lounge / smoke room

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.22 - Accommodation Spaces - Crew mess room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.23 - Accommodation Spaces - Crew lounge / smoke room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.24 - Accommodation Spaces - Welfare equipment

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.25 - Accommodation Spaces - Deck office / Cargo control room and its equipments

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.26 - Accommodation Spaces - Conference room

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.27 - Accommodation Spaces - Engineers office

Answer Detail Grade - No

Answer Remark NA



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.28 - Accommodation Spaces - Store rooms and lockers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.29 - Accommodation Spaces - Cable ducts

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.06 - Part VI - Accommodation Spaces

Question 01.06.30 - Accommodation Spaces - Garbage bins

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.01 - Navigation Bridge - General maintenance and house keeping

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.02 - Navigation Bridge - Chart room

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.03 - Navigation Bridge - Battery room

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.04 - Navigation Bridge - Navigation light masts and fittings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.05 - Navigation Bridge - Magnetic Compass - standard / gyro and repeaters

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.06 - Navigation Bridge - Auto Pilot

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.07 - Navigation Bridge - Helm indicators - inside wheelhouse and on bridge wings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.08 - Navigation Bridge - Tachometers - inside wheelhouse and on bridge wings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.09 - Navigation Bridge - Deck IG manometer

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.10 - Navigation Bridge - Radars and ARPA

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.11 - Navigation Bridge - VHF

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.12 - Navigation Bridge - Echo sounder

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.13 - Navigation Bridge - AIS

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.14 - Navigation Bridge - SSAS

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.15 - Navigation Bridge - BNWAS

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.16 - Navigation Bridge - Voyage data recorder

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.17 - Navigation Bridge - Speed log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.18 - Navigation Bridge - GPS / Satellite Navigator

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.19 - Navigation Bridge - Chronometer

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.20 - Navigation Bridge - Barometer

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.21 - Navigation Bridge - Sextants

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.22 - Navigation Bridge - Binoculars

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.23 - Navigation Bridge - Aldis lamp

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.24 - Navigation Bridge - Flags

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.25 - Navigation Bridge - Charts and status of correction

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.26 - Navigation Bridge - ECDIS

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.27 - Navigation Bridge - Nautical Publications

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.28 - Navigation Bridge - Notices to Mariners

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.29 - Navigation Bridge - Technical Library

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.30 - Navigation Bridge - Radio room

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.31 - Navigation Bridge - Main transmitter / Main Receiver

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.32 - Navigation Bridge - Emergency transmitter / Emergency Receiver

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.33 - Navigation Bridge - GMDSS Walkie Talkies

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.34 - Navigation Bridge - GMDSS VHF DSC (Operation)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.35 - Navigation Bridge - GMDSS batteries

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.36 - Navigation Bridge - Satcom / GMDSS terminal

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.37 - Navigation Bridge - Computer / UPS / Stabilizer

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.07 - Part VII - Navigation Bridge

Question 01.07.38 - Navigation Bridge - Hospital alarm

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.01 - Engine Room - Housekeeping and general maintenance

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02a - Engine Room - Main engine - Turbo charger

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02b - Engine Room - Main engine - Control stand

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02c - Engine Room - Main engine - Thrust block

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02d - Engine Room - Main engine - Shaft bearings

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02e - Engine Room - Main engine - Shaft tunnel

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02f - Engine Room - Main engine - Turning gear system

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02g - Engine Room - Main engine - Crankcase doors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02h - Engine Room - Main engine - Under Piston area

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02i - Engine Room - Main engine - Scavenge space

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02j - Engine Room - Main engine - Exhaust manifold

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02k - Engine Room - Main engine - Fuel oil booster pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02l - Engine Room - Main engine - Fuel oil heating system

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02m - Engine Room - Main engine - L.O.pumps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02n - Engine Room - Main engine - Alarms and Trips

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02o - Engine Room - Main engine - Air cooler manometers

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02p - Engine Room - Main engine - Uptake manometers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02q - Engine Room - Main engine - Sheathing on HP fuel pipes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02r - Engine Room - Main engine - Spark arrestors on exh. uptakes

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02s - Engine Room - Main engine - Exh. boiler gas passage drains clear

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.02t - Engine Room - Main engine - T/C gas passage drains clear

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.03 - Engine Room - Main S.W pumps

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.04 - Engine Room - Cooling F.W pumps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.05 - Engine Room - Fire pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.06 - Engine Room - Bilge pump

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.07 - Engine Room - General Service pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.08 - Engine Room - Ballast pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.09 - Engine Room - Bilge & floor plates (safety aspects and cleanliness)

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.10 - Engine Room - Fuel oil transfer pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.11 - Engine Room - L.O transfer pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.12 - Engine Room - Sludge pump

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.13 - Engine Room - Domestic F.W pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.14 - Engine Room - Sanitary water pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.15 - Engine Room - Fridge cooling pump

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.16 - Engine Room - A/C S.W pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.17 - Engine Room - Harbor service pump

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.18 - Engine Room - All S.W. valves

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.19 - Engine Room - Tank top

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.20 - Engine Room - Piping - general and in bilge areas

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.21 - Engine Room - H.O Purifier

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.22 - Engine Room - D.O Purifier

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.23 - Engine Room - L.O Purifier

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.24 - Engine Room - Main air compressor

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.25 - Engine Room - Top up compressor

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.26 - Engine Room - Emergency air compressor

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.27 - Engine Room - Air bottles, Control air dryers

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.28 - Engine Room - M/E coolers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.29 - Engine Room - A/E coolers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.30 - Engine Room - Fuel heater & Lagging on hot fuel pipes

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.31 - Engine Room - Metal sheathing on H.P fuel pipes

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.32 - Engine Room - Viscometers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.33 - Engine Room - Hydrophore tanks

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34a - Engine Room - Aux. Engines - General condition and maintenance

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34b - Engine Room - Aux. Engines - Turbo charger

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34c - Engine Room - Aux. Engines - Alarms and trips

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34d - Engine Room - Aux. Engines - Crankcase doors

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34e - Engine Room - Aux. Engines - Pressure and Temperature gauges

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34f - Engine Room - Aux. Engines - Nozzle cooling pump

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34g - Engine Room - Aux. Engines - Attached F.W. pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34h - Engine Room - Aux. Engines - Nozzle cooling pump

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34i - Engine Room - Aux. Engines - Governor

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34j - Engine Room - Aux. Engines - Exh. pipe lagging / metal sheathing

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34k - Engine Room - Aux. Engines - F.W. / L.O. Coolers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34l - Engine Room - Aux. Engines - Floor plates under A/Es clean & oil free?

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34m - Engine Room - Aux. Engines - m. Deck-head & pipes / cables above A/Es clean and oil free?

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.34n - Engine Room - Aux. Engines - n. Auto temperature controllers L.O. / F.W. temp

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.35 - Engine Room - Alternators

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.36 - Engine Room - Motors / starters

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.37 - Engine Room - Main switchboard

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.38 - Engine Room - Emergency switchboard

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.39 - Engine Room - Cable trays

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.40 - Engine Room - Emergency Generator / Batteries

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.41 - Engine Room - Fridge compressor

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.42 - Engine Room - Condensers / coolers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.43 - Engine Room - Thermostatic valves

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.44 - Engine Room - Coils / fans

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.45 - Engine Room - E/R blowers

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.46 - Engine Room - Engine Control Room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.47 - Engine Room - F.W generator

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.48 - Engine Room - Oily water separator

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.49 - Engine Room - Sewage Plant

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.50 - Engine Room - Incinerator

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51a - Engine Room - Boilers (steam and thermal oil) - Condition and general maintenance

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51b - Engine Room - Boilers (steam and thermal oil) - Feed water pumps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51c - Engine Room - Boilers (steam and thermal oil) - Circulation pump

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51d - Engine Room - Boilers (steam and thermal oil) - Safety valve

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51e - Engine Room - Boilers (steam and thermal oil) - Gauge glass

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51f - Engine Room - Boilers (steam and thermal oil) - Automatic Combustion. C

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51g - Engine Room - Boilers (steam and thermal oil) - F.D. fan

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51h - Engine Room - Boilers (steam and thermal oil) - Boiler uptake lagging

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51i - Engine Room - Boilers (steam and thermal oil) - All temperature and pressure gauges

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51j - Engine Room - Boilers (steam and thermal oil) - F.O. pump

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51k - Engine Room - Boilers (steam and thermal oil) - F.O. heater

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51l - Engine Room - Boilers (steam and thermal oil) - Lagging on hot fuel oil and Heating steam pipes

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51m - Engine Room - Boilers (steam and thermal oil) - Steam dump valve and other steam valves

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.51n - Engine Room - Boilers (steam and thermal oil) - Warning notices and operating instructions

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52a - Engine Room - IG system - IG generator

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52b - Engine Room - IG system - IG control panel and control system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52c - Engine Room - IG system - Pneumatic system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52d - Engine Room - IG system - IG blower

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52e - Engine Room - IG system - Scrubber unit

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.52f - Engine Room - IG system - Oxygen analyzer

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.53 - Engine Room - Soot blower

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.54 - Engine Room - Exhaust boiler

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55a - Engine Room - COP turbines - Condition and general maintenance

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55b - Engine Room - COP turbines - Alarms and trips

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55c - Engine Room - COP turbines - governor

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55d - Engine Room - COP turbines - L.O. pump

Answer Detail Grade - No

Answer Remark MA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55e - Engine Room - COP turbines - L.O. cooler

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55f - Engine Room - COP turbines - Control panel

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55g - Engine Room - COP turbines - Tachometer

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.55h - Engine Room - COP turbines - Local temp and pressure gauges

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.56 - Engine Room - Vacuum condenser

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.57 - Engine Room - Condenser S.W. pump

Answer Detail Grade - No

Answer Remark NA

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.58 - Engine Room - Hot well

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.59 - Engine Room - CO2 room

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.60 - Engine Room - Quick closing valves

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.61 - Engine Room - Remote switches and cut-offs

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.62 - Engine Room - Sky light

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.63 - Engine Room - Blower flaps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.64 - Engine Room - Steering flat

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.65 - Engine Room - Storage of chemicals

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.66 - Engine Room - Workshop

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.67 - Engine Room - E/R crane

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.68 - Engine Room - Stores

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.69 - Engine Room - Spares

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.70 - Engine Room - Tools / instruments

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.08 - Part VIII - Engine Room

Question 10.08.71 - Engine Room - LO and water treatment test kits

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.01 - Record Keeping - Deck Log Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.02 - Record Keeping - Official Log Book

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.03 - Record Keeping - Night Order Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.04 - Record Keeping - Movement (Bell) Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.05 - Record Keeping - Sounding Book

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.06 - Record Keeping - Compass error Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.07 - Record Keeping - Chronometer Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.08 - Record Keeping - Radio Log

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.09 - Record Keeping - Radar Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.10 - Record Keeping - Chart correction folio

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.11 - Record Keeping - Garbage Log

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.12 - Record Keeping - Videotel / Training Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.13 - Record Keeping - Calibration Log

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.14 - Record Keeping - Stores inventory (deck and saloon)

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.15 - Record Keeping - Spare Part Inventory (Deck)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.16 - Record Keeping - Planned Maintenance Records(Deck, Radio, Safety Equipment)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.17 - Record Keeping - Masters Filing System

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.18 - Record Keeping - Chief Engineers Filing System

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.19 - Record Keeping - E/R Log Book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.20 - Record Keeping - Oil Record Book

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.21 - Record Keeping - E/R tank sounding book

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.22 - Record Keeping - Survey records / Quarterly listing

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.23 - Record Keeping - Spare Part Inventory (E/R)

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.24 - Record Keeping - Planned Maintenance Records (Main, Aux. and Electrical machinery)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.09 - Part IX - Record Keeping

Question 10.09.25 - Record Keeping - Ships drawings and manuals

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.01 - Certificates and Approvals - Statutory certificates as per Form D-13

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.02 - Certificates and Approvals - Type approval Certificates for L/Jackets, L/Buoys, Pyrotechnics, Navigation Lights,

Sound Signal equipment, shapes, fireman's outfits, fire detection system, alarms, ODME, ODMCS, Sewage plant

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.03 - Certificates and Approvals - Wires and Ropes Test Certificates

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.04 - Certificates and Approvals - Chain Register

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.05 - Certificates and Approvals - Life raft Certificate

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.10 - Part X - Certificates And Appr

Question 10.10.06 - Certificates and Approvals - Administration approved LSA, LSS and FFA plans

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.01 - Safety Equipment and Alarms - General Alarm

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.02 - Safety Equipment and Alarms - Fire detection system (Accommodation/E.R/Cargo holds)

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.03 - Safety Equipment and Alarms - Hospital Bell

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.04 - Safety Equipment and Alarms - Medical locker / equipment

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.05 - Safety Equipment and Alarms - Fridge room alarm

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.06 - Safety Equipment and Alarms - E/R Bilge High level alarms

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.07 - Safety Equipment and Alarms - CO2 / Halon release alarm

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.08 - Safety Equipment and Alarms - Vent fans flaps / funnel flaps / Remote closing flaps

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.09 - Safety Equipment and Alarms - Fixed foam system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.10 - Safety Equipment and Alarms - Portable foam system

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.11 - Safety Equipment and Alarms - Steam smothering

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.12 - Safety Equipment and Alarms - Inert gas system

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.14 - Safety Equipment and Alarms - Fire mains / hydrants

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.15 - Safety Equipment and Alarms - Hoses / nozzles

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.16 - Safety Equipment and Alarms - Pollution Locker and equipments

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.17 - Safety Equipment and Alarms - Emergency fire pump

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.18 - Safety Equipment and Alarms - Emergency generator

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.19 - Safety Equipment and Alarms - Emergency lights

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.20 - Safety Equipment and Alarms - Life boat operation

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.21 - Safety Equipment and Alarms - Life boat equipment

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.22 - Safety Equipment and Alarms - Life boat engines

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.23 - Safety Equipment and Alarms - Extinguishers - Foam, Water, DCP, CO2

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.24 - Safety Equipment and Alarms - Tankscope, Explosimeter, O2 analyzer and Toxic gas detector

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.25 - Safety Equipment and Alarms - Breathalyzer

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.26 - Safety Equipment and Alarms - CABA, Resuscitation equipment

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.27 - Safety Equipment and Alarms - Fireman's outfit with accessories

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.11 - Part XI - Safety Equipment And

Question 10.11.28 - Safety Equipment and Alarms - Emergency Towing System

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 10.12.01 - Environmental - Ballast water management

Answer Detail Grade - Yes



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 10.12.02 - Environmental - Garbage management

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 10.12.03 - Environmental - Ship Energy efficiency plan

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.12 - Part XII - Environmental

Question 10.12.04 - Environmental - Safety Meeting conducted with entire crew by Superintendent

Answer Detail Grade - No



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.01 - Security - Ship Security Records

Answer Detail BEING MAINTAINED

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.02 - Security - Security Equipments

Answer Detail Grade - Yes

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.03 - Security - Security Communications and SSAS

Answer Detail 2ND SEPTEMBER 2019



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.04 - Security - Vessel Hardening

Answer Detail ON BOARD

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.05 - Security - Security Charts, Publications and Guidance

Answer Detail ON BOARD

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.06 - Security - Cyber Security incl. Access to IT/OT Terminals, Workstation Security etc.

Answer Detail UNDER PROGRESS



Vessel - Bitu Atlantic (IMO: 9382085)

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.07 - Security - Cyber Response Plan

Answer Detail NOT ONBOARD

Answer Remark

Chapter 01.00 - Area/Item Inspected

Category 01.13 - Part XIII - Security

Question 10.13.08 - Security - Personal Devices usage

Answer Detail night vision Binocular, bullet proof jacket, metal Detector